

TP III

Xiao Tong

SJK8827C 2008 Nov

Honda Stream 1799cc

RN61084875.

Front Number Plate	crushed	30(SN)	/
Front Bumper	Distorted	685.60	/
Front Bumper Clips	new	30(SN)	/
Front Bumper Side Holder x 02	2nd Distorted	$24.5 \times 2 = 49$	/
Front Bumper Lower Grille		123.50	/
Front Bumper Side Grille	AP m	$67.1 \times 2 = 134.20$	+
Front Bumper Reinforcement	Distorted	245.60	/
Front Bumper Lower Spoiler	smashed	1000(SN) 700(SN)	/
Front Grille	smashed	480(SN) 350(SN)	/
Front Grille Clips	m	20(SN)	/
Headlamp x 02	crushed	$680.4 \times 2 = 1360.80$	/
Headlamp lower Bracket x 02	crushed	$65.9 \times 2 = 131.80$	/
Bonnet	Buckled	686.90	/
Bonnet Lock	Damaged	85.10	/

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledge by Repairer

Signature:

Date:

SIK 8827C

Bonnet Hinge x 02 Bent	45.2 x 2 = 90.40 ✓
Bonnet Insulator	110.20. ✗
Bonnet Insulator Clips	30(SN) ✗
Bonnet Weatherstripe	48.50 ✗
Bonnet Weatherstripe Clips.	20(SN) ✗
Front Support Panel	Distorted 628.40 ✓
Front Support Panel Top Cover	Distorted 125.40. ✓
Front Support Panel Top Cover Clips.	20(SN) ✓
Air Con Condenser	Distorted 826.40 ✓
Air Con Condenser Top Mounting x 02	26 x 2 = 52 ✓
Air Con Condenser Rear Mounting x 02	28 x 2 = 56 ✓
Air Con Discharge Pipe Bent	264.90 ✓
Air Con Suction Pipe Bent	282.30 ✓
Air Con Liquid Pipe Bent	195.40 ✓

SJK8827c

Air Car Fan Cowling	Distorted	85.10	✓
Air Car Fan Blade	new	68.60	+
Air Car Fan Motor	Distorted	308.80	✓
Radiator	Distorted	1483.10	✓
Radiator Top Bracket x 02	Distorted	29 x 2 = 58	✓
Radiator Lower Mounting x 02	Distorted	27 x 2 = 54	+
Radiator Spare Tank	Distorted	68.40	✓
Radiator Coolant	new	40(SN)	✓
Radiator Fan Cowling	new	109.40	✓
Radiator Fan Blade	new	68.40	+
Radiator Fan Motor	Distorted	316	✓
Battery Cover	Distorted	84.10	✓
Battery Lower Tray	Distorted	65.80	✓
Battery	new	250(SN)	+
Air Cleaner Housing	new	310.80	✓
Air Cleaner Hose	new	98.70	+
Fuse Box	new	455.70	+

SIK 8827C

Engine Mounting x 02	new	$2 \times 8.9 \times 2 = 537.80$	x
Engine Mounting Bracket		128.90	x
Front Fender x 02	Rehd	$486.2 \times 2 = 972.40$	
Front Fender Top Garnish x 02	Rehd	$36.5 \times 2 = 73$	-
Front Fender Top Garnish Clips.	new	30(SN)	/
Front Fender Inner Shield x 02	new	$142.4 \times 2 = 284.80$	+
Front Fender Inner Shield clips.	new	60(SN)	x
Engine Undercover	new	158.60.	-
Engine Undercover Clips.	new	30(SN)	/
Rocker Panel Outer Skirting HH.	new	680(SN) 500(SN)	
Rocker Panel Outer Skirting Clips.	new	30(SN)	/
Front Sub Frame.	new	1181.70	x
Roof Side Moulding x 02	new	$197.2 \times 2 = 394.40$	+
Roof Side Moulding clips.	new	60(SN)	x
Wiper Panel Garnish	new	185.60	f

SJK 8827C

Intake Manifold Heat Shield	$\overline{M}$	90.10.	x
Radiator Top Hose	twisted	45.40.	✓
Radiator lower Hose	$\overline{M}$	39.40.	x
Engine ECU	$\overline{M}$	1431.40.	x
Engine ECU Cover.	$\overline{M}$	86.40	x
Air Bag Sensor x 02		$189.9 \times 2 = 379.80$	
Air Bag ECU.	Activated	1308.50	✓
Safety Belt x 02		$694 \times 2 = 1388$	✓
Steering Wheel Air Bag	Activated	1890.90	✓
Steering Wheel Anti-Clock Spring.	Activated	325.40	✓
Dashboard	torn	768.80.	✓
Dashboard Air Bag	Activated	2236.80	
Radio Console	used	485.50	✓
Air Resonator	smashed	240.40	✓

18997.50

S.N. 1780

15/584

STK 8827C.

Panel Beating.

~~2000~~ 1200

Spray Painting.

~~1800~~ 1000

Wiring.

~~200~~ 30

To spray tuff coat.

~~150~~ 60.

To remove condenser and }
to top up air con gas |.

~~120~~ 60

To remove radiator and }
to top up coolant |.

~~120~~ 60.

To dismantle front undercarriage.

400 X

To remove safety belts.

~~250~~ 180.

To remove dashboard.

~~350~~ 200.

To remove air bags. and }
to perform diagnostic test |.

~~480~~ 300

3150

To replace engine mountings

300 X

Towing Charges. 3150

60 ✓

Total 20128

n/s. 16.1K. 10 Dup