

## **Accident Scene Location**

Your insured (FBR5356Y) dashed out from the carpark exit of Blk 100 – 106 Carpark without checking for oncoming vehicles along the 2-way traffic road at Bedok North Avenue 4. Due to your insured's negligence, he collided into our client's vehicle and pull out the front bumper while our client was travelling straight within his lane at that point in time.

See below accident scene photos.





