



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967					
		Document No. 0						
		Document Date 27/09/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM / <i>KL</i> TP-GV8627R ACC DATE:27/09/2021 TOW IN:27/09/2021 DATE-IN:27/09/2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:						30.00 ✓
2	B	BP-LAB2	DRILL HOLE & INSTALL REAR REVERSE SENSOR					180.00 ✓
3	B	BP-LAB2	CHECK LIGHTING & CONDUCT WATER LEAK TEST					180.00 ✓
4	B	BP-LAB2	REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR					360.00 ✓
5	Z	BP-SLANT	SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL / <i>KL</i>					120.00 ✓
6	B	BP-LAB2	REPLACE & INSTALL REAR WINDSCREEN GLASS					462.00 ✓
7	S	BP-SUBLET	INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM / <i>NBC</i>					350.00 ✓
8	B	BP-LAB2	REMOVE & INSTALL REAR REVERSE CAMERA					180.00 ✓
9	B	BP-LAB2	TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE					360.00 ✓
10	S	BP-SUBLET	TO RESET ECU AND REPROGRAMME					180.00 ✓
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hwe Soon Kheng				
		Document No. 0	15 Fernvale Close #18-26 Singapore 797477				
		Document Date 27/09/2021	Mobile: 98392967				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	677TP/SMA/877G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH50J002140		8ARZ122346	60	Sam San Jol	- / - / - -		0 00 - / - / - - 0 00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	720			3240	4320 00
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				2950	3540 00
13	1	T52159-48933 COVER, RR BUMPER	1.00	904 00			904 00
14	2	T52156-48050 SUPPORT, RR BUMPER	1.00	82 70			82 70
15	3	T52155-48050 SUPPORT, RR BUMPER	1.00	82 70			82 70
16	4	T52169-48100 COVER, RR BUMPER	1.00	466 00			466 00
17	5	S52161-0K040 CLIPS	10.00	4 10			41 00
18	6	T52163-48050 PLATE, RR BUMPER, RH	1.00	98 20			98 20
19	7	T52615-48230 ABSORBER, RR BUMPER	1.00	122 60			122 60
20	8	T58307-48120 PANEL SUB-ASSY, BODY	1.00	1006 40			1006 40
21	9	T48691-48030 DAMPER, SUSPENSION	1.00	1343 10			1343 10
22	0	T64716-48020 C0 COVER, DECK TRIM, RR	1.00	438 30			438 30
23	1	T58410-48120 C0 BOARD ASSY, DECK	1.00	885 50			885 50
24	2	T64779-48060 TRAY, SPARE WHEEL	1.00	782 20			782 20
25	3	T67005-48350 PANEL SUB-ASSY, BACK	1.00	2378 00			2378 00
26	4	T67881-48070 WEATHERSTRIP, BACK	1.00	441 30			441 30
27	5	T68105-48905 GLASS SUB-ASSY, BACK	1.00	1230 40			1230 40
28	6	T75575-48040 MOULDING, BACK	1.00	51 90			51 90
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary			Total	
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others			Less Amount Due	

Customer Copy



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967				
		Document No. 0					
		Document Date 27/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	7	T67750-48010 C0 BOARD ASSY, BACK ?	1.00	578.50		578.50	
30	8	T69350-48063 LOCK ASSY, BACK DOOR ?	1.00	974.00		974.00	
31	9	T69430-48030 STRIKER ASSY, BACK X nrv	1.00	41.40		41.40	
32	0	T90975-02071 EMBLEM, SYMBOL	1.00	57.90		57.90	
33	1	T75442-48140 PLATE, BACK DOOR	1.00	73.70		73.70	
34	2	SPZQ31-13020 Badge Assy, Engine Mark RHS	1.00	17.52		17.52	
35	3	T76801-48510 A0 GARNISH SUB-ASSY, - ne	1.00	1055.20		1055.20	
36	4	T81561-48421 LENS & BODY, RR ?	1.00	667.70		667.70	
37	5	T81551-48431 LENS & BODY, RR	1.00	667.70		667.70	
38	6	T81591-48261 LENS & BODY, RR	1.00	506.70		506.70	
39	7	T81581-48251 LENS & BODY, RR	1.00	506.70		506.70	
40	8	T52563-48010 RETAINER, RR BUMPER, - ne	1.00	121.10		121.10	
41	9	T52562-48010 RETAINER, RR BUMPER, - ne	1.00	121.10		121.10	
42	0	L81920-48012 REFLECTOR ASSY, X nrv	1.00	60.40		60.40	
43	1	T81910-48012 R/RR BPR REFLECTOR ASSY, - CRA	1.00	60.40		60.40	
44	2	T89341-58060 A0 SENSOR, ULTRASONIC, - DM	2.00	481.90		1927.60	
45	3	T89348-58070 A0 RETAINER, ULTRASONIC - CRA	2.00	21.30		85.20	
46	4	T89348-58120 RETAINER, ULTRASONIC - CRA	4.00	16.00		64.00	
47	5	T89997-30100 ANTENNA, ELECTRICAL ?	1.00	72.60		72.60	
48	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA - ne	2.00	108.00		216.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967
	Document No. 0	
	Document Date 27/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH50J002140	8ARZ122346	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER / <i>ka</i>	1.00	200.00		200.00
50	8	T17408-46020 BAFFLE SUB-ASSY, ?	1.00	154.20		154.20
51	9	T17430-36550 PIPE ASSY, EXHAUST ?	1.00	767.00		767.00

*8 Days
before parts photos.
Gao Qian
28/9/2021*

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	29,612.92
	Please acknowledge receipt of vehicle	Parts 19,350.92	GST 7.00%	2,072.90
		Labour 9,732.00	Less	0.00
		Sublet 530.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	31,685.82

Customer Copy