



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details						
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967						
		Document No. 0							
		Document Date 27/09/2021							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM / <i>KL</i> TP-GV8627R ACC DATE:27/09/2021 TOW IN:27/09/2021 DATE-IN:27/09/2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:							✓ 30.00 ✓
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR							✓ 180.00 ✓
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST							✓ 180.00 ✓
4	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR							✓ 360.00 ✓
5	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL / <i>KL</i>							✓ 120.00 ✓
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS							✓ 462.00 ✓
7	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM / <i>NBC</i>							✓ 350.00 ✓
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA							✓ 180.00 ✓
9	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE							✓ 360.00 ✓
10	S	BP-SUBLET TO RESET ECU AND REPROGRAMME							✓ 180.00 ✓
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hwe Soon Kheng	
		Document No. 0	15 Fernvale Close #18-26 Singapore 797477	
		Document Date 27/09/2021	Mobile: 98392967	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	677TP/SMA/877G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH50J002140	8ARZ122346	60	Sam San Jol	- / - / -	0.00 - / - / - 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS <i>720</i>			✓ <i>3240</i>	4,320.00 4320.00
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS			✓ <i>2950</i>	3540.00 3540.00
13	1	T52159-48933 COVER, RR BUMPER <i>Re</i>	1.00	904.00	904.00	✓ 904.00
14	2	T52156-48050 SUPPORT, RR BUMPER <i>X NN</i>	1.00	82.70	82.70	✓ 82.70
15	3	T52155-48050 SUPPORT, RR BUMPER <i>cut</i>	1.00	82.70	82.70	✓ 82.70
16	4	T52169-48100 COVER, RR BUMPER, <i>Re</i>	1.00	466.00	466.00	✓ 466.00
17	5	S52161-0K040 CLIPS <i>Re</i>	10.00	4.10	41.00	✓ 41.00
18	6	T52163-48050 PLATE, RR BUMPER, RH <i>Re</i>	1.00	98.20	98.20	✓ 98.20
19	7	T52615-48230 ABSORBER, RR BUMPER <i>buc</i>	1.00	122.60	122.60	✓ 122.60
20	8	T58307-48120 PANEL SUB-ASSY, BODY	1.00	1006.40	1006.40	✓ 1006.40
21	9	T48691-48030 DAMPER, SUSPENSION <i>X NN</i>	1.00	1343.10	1343.10	✓ 1343.10
22	0	T64716-48020 C0 COVER, DECK TRIM, RR <i>Re</i>	1.00	438.30	438.30	✓ 438.30
23	1	T58410-48120 C0 BOARD ASSY, DECK <i>X NN</i>	1.00	885.50	885.50	✓ 885.50
24	2	T64779-48060 TRAY, SPARE WHEEL <i>X NN</i>	1.00	782.20	782.20	✓ 782.20
25	3	T67005-48350 PANEL SUB-ASSY, BACK <i>Re</i>	1.00	2378.00	2378.00	✓ 2378.00
26	4	T67881-48070 WEATHERSTRIP, BACK <i>Re</i>	1.00	441.30	441.30	✓ 441.30
27	5	T68105-48905 GLASS SUB-ASSY, BACK <i>Re</i>	1.00	1230.40	1230.40	✓ 1230.40
28	6	T75575-48040 MOULDING, BACK <i>Re</i>	1.00	51.90	51.90	✓ 51.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Parts	
	Please acknowledge receipt of vehicle	Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967					
		Document No. 0						
		Document Date 27/09/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	7	T67750-48010 C0 BOARD ASSY, BACK NN			1.00	578.50		578.50
30	8	T69350-48063 LOCK ASSY, BACK DOOR NN			1.00	974.00		974.00
31	9	T69430-48030 STRIKER ASSY, BACK NN			1.00	41.40		41.40
32	0	T90975-02071 EMBLEM, SYMBOL			1.00	57.90		57.90
33	1	T75442-48140 PLATE, BACK DOOR			1.00	73.70		73.70
34	2	SPZQ31-13020 Badge Assy, Engine Mark RHS			1.00	17.52		17.52
35	3	T76801-48510 A0 GARNISH SUB-ASSY, de			1.00	1055.20		1055.20
36	4	T81561-48421 LENS & BODY, RR NN			1.00	667.70		667.70
37	5	T81551-48431 LENS & BODY, RR			1.00	667.70		667.70
38	6	T81591-48261 LENS & BODY, RR			1.00	506.70		506.70
39	7	T81581-48251 LENS & BODY, RR			1.00	506.70		506.70
40	8	T52563-48010 RETAINER, RR BUMPER, de			1.00	121.10		121.10
41	9	T52562-48010 RETAINER, RR BUMPER, NN			1.00	121.10		121.10
42	0	L81920-48012 REFLECTOR ASSY, NN			1.00	60.40		60.40
43	1	T81910-48012 R/RR BPR REFLECTOR ASSY, CRA			1.00	60.40		60.40
44	2	T89341-58060 A0 SENSOR, ULTRASONIC, DM			2.00	481.90		963.8 1927.60
45	3	T89348-58070 A0 RETAINER, ULTRASONIC, de			2.00	21.30		42.6 85.20
46	4	T89348-58120 RETAINER, ULTRASONIC			4.00	16.00		64.00
47	5	T89997-30100 ANTENNA, ELECTRICAL NN			1.00	72.60		72.60
48	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA de			2.00	108.00		216.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	Amount Due
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No	Customer Details
India International Insurance P L	S1000006 / ICIII1	Mr Hoe Soon Kheng
64 Cecil Street	Document No.	15 Fernvale Close
#06-02 IOB Building	0	#18-26
Singapore 049711	Document Date	Singapore 797477
Attn: Motor Claims Dept	27/09/2021	Mobile: 98392967

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH50J002140	8ARZ122346	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	7	T21000-22 Sika 207. G+P ADHESIVE PRIMER	1.00	200.00		✓ 200.00
50	8	T17408-46020 BAFFLE SUB-ASSY, ✓ NEC	1.00	154.20		✓ 154.20
51	9	T17430-36550 PIPE ASSY, EXHAUST ✓ BT	1.00	767.00		✓ 767.00

9 ~~8~~ Days
before parts photos.
Gino Qian
28/9/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts 19,350.92	29,612.92
		Labour 9,732.00	GST 7.00% 2,072.90
		Sublet 530.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 31,685.82

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967				
			Document No. 39012175						
			Document Date 25/10/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021 17.07		25/10/2021 14.58		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-GV8627R ACC DATE:27/09/2021 TOW IN:27/09/2021 DATE-IN:27/09/2021 DATE SURVEY:28/09/2021 NO OF REPAIR DAYS:9 DAYS BY:GUO QIANG(LKK)							30.00
2	B	BP-LAB2	DRILL HOLE & INSTALL REAR REVERSE SENSOR		*				180.00
3	B	BP-LAB2	CHECK LIGHTING & CONDUCT WATER LEAK TEST		*				180.00
4	B	BP-LAB2	REMOVE & INSTALL REAR COMPARTMENT CARPET		BP56				360.00
5	Z	BP-SLANT	SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL						120.00
6	B	BP-LAB2	REPLACE & INSTALL REAR WINDSCREEN GLASS		BP56				462.00
7	S	BP-SUBLET	INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM		0741				350.00
8	B	BP-LAB2	REMOVE & INSTALL REAR REVERSE CAMERA		BP56				180.00
9	B	BP-LAB2	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE		*				360.00
10	S	BP-SUBLET	TO RESET ECU AND REPROGRAMME		0742				180.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details					
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng					
		Document No. 39012175	15 Fernvale Close #18-26 Singapore 797477					
		Document Date 25/10/2021	Mobile: 98392967					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021 17.07		25/10/2021 14.58	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2	REPLACE REAR ACCIDENT DAMAGED PARTS			BP56		3240.00
			STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS					
12	B	BP-RES2	RESPRAY JOB ON REAR ACCIDENT AFFECTED AR			*		2950.00
		EAS						
13	S	BP-SUBLET	REPLACE & INSTALL REAR EXHAUST PIPE ASSY			SUPP 0742		360.00
14	1	T52159-48933	COVER, RR BUMPER			1.00	904.00	904.00
15	2	T52155-48050	SUPPORT, RR BUMPER			1.00	82.70	82.70
16	3	T52169-48100	COVER, RR BUMPER,			1.00	466.00	466.00
17	4	S52161-0K040	PIECE, RR BUMPER			10.00	4.10	41.00
18	5	T52163-48050	PLATE, RR BUMPER, RH			1.00	98.20	98.20
19	6	T52615-48230	ABSORBER, RR BUMPER			1.00	122.60	122.60
20	7	T58307-48120	PANEL SUB-ASSY, BODY			1.00	1006.40	1006.40
21	8	T64716-48020 C0	COVER, DECK TRIM, RR			1.00	438.30	438.30
22	9	T67005-48350	PANEL SUB-ASSY, BACK G			1.00	2378.00	2378.00
23	0	T67881-48070	WEATHERSTRIP, BACK			1.00	441.30	441.30
24	1	T68105-48905	GLASS SUB-ASSY, BACK			1.00	1230.40	1230.40
25	2	T75575-48040	MOULDING, BACK			1.00	51.90	51.90
26	3	T90975-02071	EMBLEM,SYMBOL			1.00	57.90	57.90
27	4	T75442-48140	PLATE, BACK DOOR			1.00	73.70	73.70
28	5	SPZQ31-13020	Badge Assy, Engine Mark RHS (AUD)			1.00	17.52	17.52
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
Amount Due								

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng				
		Document No. 39012175	15 Fernvale Close #18-26 Singapore 797477				
		Document Date 25/10/2021	Mobile: 98392967				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021 17.07		25/10/2021 14.58
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	6	T76801-48510 C1 GARNISH SUB-ASSY,	1.00	1055.20		1055.20	
30	7	T81551-48431 LENS & BODY, RR	1.00	667.70		667.70	
31	8	T81591-48261 LENS & BODY, RR	1.00	506.70		506.70	
32	9	T81581-48251 LENS & BODY, RR	1.00	506.70		506.70	
33	0	T52562-48010 RETAINER, RR BUMPER,	1.00	121.10		121.10	
34	1	S81910-0K030 REFLECTOR ASSY,RH	1.00	60.40		60.40	
35	2	T89341-58060 A0 SENSOR, ULTRASONIC,	1.00	481.90		481.90	
36	3	T89348-58070 A0 RETAINER, ULTRASONIC	2.00	21.30		42.60	
37	4	T89348-58120 RETAINER, ULTRASONIC	4.00	16.00		64.00	
38	5	T21000-20 SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00		216.00	
39	6	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIMER	1.00	200.00		200.00	
40	7	T17408-46020 BAFFLE SUB-ASSY,	1.00	154.20		154.20	
41	8	T17430-36550 PIPE ASSY, EXHAUST	1.00	767.00		767.00	
42	9	T89341-58060 D1 SENSOR, ULTRASONIC,	1.00	481.90		481.90	
43	0	T58578-48020 PLATE, RR FLOOR MAT ✓ BT	1.00	576.40		576.40	
44	1	T58577-48010 PLATE, RR FLOOR MAT ✓ BT	1.00	487.80		487.80	
45	2	T64997-48010 BOX, DECK FLOOR, LH ✓ CRA	1.00	640.50		640.50	
46	3	T64779-48060 TRAY, SPARE WHEEL ✓ DE	1.00	782.20		782.20	
47	4	T64995-48010 BOX, DECK FLOOR, RH ✓ DE	1.00	444.20		444.20	
48	5	T64730-48120 C0 PANEL ASSY, DECK ✓ DE	1.00	718.00		718.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid		Amount Due		
			Others				

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept				S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967			
				Document No. 39012175					
				Document Date 25/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021	17.07	25/10/2021	14.58	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
49	6	T58410-48120 C0 BOARD ASSY, DECK ✓ DE				1.00	885.50		885.50
50	7	T58401-48030 C1 BOARD SUB-ASSY, DECK ✓ DE				1.00	692.90		692.90
51	8	T67767-48020 C0 COVER, BACK DOOR ✓ CRA				1.00	47.10		47.10
52	9	T51931-47020 CARRIER, SPARE ✓ BT				1.00	21.10		21.10
53	0	T48691-48030 DAMPER, SUSPENSION ✓ BT				1.00	1343.10		1343.10
54	1	T69350-48063 LOCK ASSY, BACK DOOR ✓ CUT				1.00	974.00		974.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary			Total 29,300.12		
		Please acknowledge receipt of vehicle 		Parts	20,348.12	GST 7.00% 2,051.01			
				Labour	8,062.00				
				Sublet	890.00	Less 0.00			
				Lubrication/Fluid	0.00				
				Others	0.00	Amount Due 31,351.13			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967				
			Document No. 39012175						
			Document Date 25/10/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021 17.07		25/10/2021 14.58		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-GV8627R ACC DATE:27/09/2021 TOW IN:27/09/2021 DATE-IN:27/09/2021 DATE SURVEY:28/09/2021 NO OF REPAIR DAYS:9 DAYS BY:GUO QIANG(LKK)							30.00
2	B	BP-LAB2	DRILL HOLE & INSTALL REAR REVERSE SENSOR		*				180.00
3	B	BP-LAB2	CHECK LIGHTING & CONDUCT WATER LEAK TEST		*				180.00
4	B	BP-LAB2	REMOVE & INSTALL REAR COMPARTMENT CARPET		BP56				360.00
5	Z	BP-SLANT	SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL						120.00
6	B	BP-LAB2	REPLACE & INSTALL REAR WINDSCREEN GLASS		BP56				462.00
7	S	BP-SUBLET	INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM		0741				350.00
8	B	BP-LAB2	REMOVE & INSTALL REAR REVERSE CAMERA		BP56				180.00
9	B	BP-LAB2	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE		*				360.00
10	S	BP-SUBLET	TO RESET ECU AND REPROGRAMME		0742				180.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Hoe Soon Kheng				
		Document No. 39012175	15 Fernvale Close #18-26 Singapore 797477				
		Document Date 25/10/2021	Mobile: 98392967				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEKB3GH50J002140	8ARZ122346	60	Sam San Joi	27/09/2021 17.07	25/10/2021 14.58		
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS	BP56			3240.00	
12	B	BP-RES2 STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	*			2950.00	
13	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	0742			360.00	
14	1	T52159-48933 REPLACE & INSTALL REAR EXHAUST PIPE ASSY	1.00	904.00		904.00	
15	2	T52155-48050 COVER, RR BUMPER	1.00	82.70		82.70	
16	3	T52169-48100 SUPPORT, RR BUMPER	1.00	466.00		466.00	
17	4	S52161-0K040 COVER, RR BUMPER,	1.00	4.10		41.00	
18	5	T52163-48050 PIECE, RR BUMPER	1.00	98.20		98.20	
19	6	T52615-48230 PLATE, RR BUMPER, RH	1.00	122.60		122.60	
20	7	T58307-48120 ABSORBER, RR BUMPER	1.00	1006.40		1006.40	
21	8	T64716-48020 C0 PANEL SUB-ASSY, BODY	1.00	438.30		438.30	
22	9	T67005-48350 COVER, DECK TRIM, RR	1.00	2378.00		2378.00	
23	0	T67881-48070 PANEL SUB-ASSY, BACK G	1.00	441.30		441.30	
24	1	T68105-48905 WEATHERSTRIP, BACK	1.00	1230.40		1230.40	
25	2	T75575-48040 GLASS SUB-ASSY, BACK	1.00	51.90		51.90	
26	3	T90975-02071 MOULDING, BACK	1.00	57.90		57.90	
27	4	T75442-48140 EMBLEM,SYMBOL	1.00	73.70		73.70	
28	5	SPZQ31-13020 PLATE, BACK DOOR	1.00	17.52		17.52	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967		
			Document No. 39012175				
			Document Date 25/10/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021	17.07	25/10/2021 14.58
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	6	T76801-48510 C1 GARNISH SUB-ASSY,	1.00	1055.20		1055.20	
30	7	T81551-48431 LENS & BODY, RR	1.00	667.70		667.70	
31	8	T81591-48261 LENS & BODY, RR	1.00	506.70		506.70	
32	9	T81581-48251 LENS & BODY, RR	1.00	506.70		506.70	
33	0	T52562-48010 RETAINER, RR BUMPER,	1.00	121.10		121.10	
34	1	S81910-0K030 REFLECTOR ASSY,RH	1.00	60.40		60.40	
35	2	T89341-58060 A0 SENSOR, ULTRASONIC,	1.00	481.90		481.90	
36	3	T89348-58070 A0 RETAINER, ULTRASONIC	2.00	21.30		42.60	
37	4	T89348-58120 RETAINER, ULTRASONIC	4.00	16.00		64.00	
38	5	T21000-20 SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00		216.00	
39	6	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIMER	1.00	200.00		200.00	
40	7	T17408-46020 BAFFLE SUB-ASSY,	1.00	154.20		154.20	
41	8	T17430-36550 PIPE ASSY, EXHAUST	1.00	767.00		767.00	
42	9	T89341-58060 D1 SENSOR, ULTRASONIC,	1.00	481.90		481.90	
43	0	T58578-48020 PLATE, RR FLOOR MAT	1.00	576.40		576.40	
44	1	T58577-48010 PLATE, RR FLOOR MAT	1.00	487.80		487.80	
45	2	T64997-48010 BOX, DECK FLOOR, LH	1.00	640.50		640.50	
46	3	T64779-48060 TRAY, SPARE WHEEL	1.00	782.20		782.20	
47	4	T64995-48010 BOX, DECK FLOOR, RH	1.00	444.20		444.20	
48	5	T64730-48120 C0 PANEL ASSY, DECK	1.00	718.00		718.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept				S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477			
				Document No. 39012175					
				Document Date 25/10/2021		Mobile: 98392967			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	68698	21286	67/TP/SMA7877G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	27/09/2021	17.07	25/10/2021	14.58	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
49	6	T58410-48120 C0 BOARD ASSY, DECK				1.00	885.50		885.50
50	7	T58401-48030 C1 BOARD SUB-ASSY, DECK				1.00	692.90		692.90
51	8	T67767-48020 C0 COVER, BACK DOOR				1.00	47.10		47.10
52	9	T51931-47020 CARRIER, SPARE				1.00	21.10		21.10
53	0	T48691-48030 DAMPER, SUSPENSION				1.00	1343.10		1343.10
54	1	T69350-48063 LOCK ASSY, BACK DOOR				1.00	974.00		974.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 29,300.12		
			Please acknowledge receipt of vehicle 		Parts	20,348.12	GST 7.00%		2,051.01
					Labour	8,062.00	Less		0.00
					Sublet	890.00			
					Lubrication/Fluid	0.00			
					Others	0.00	Amount Due		31,351.13

Company Copy