

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0797/2021/JT
DATE : 28-Sep-21
WIP : 46508

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 4/10/21
YOUR INSURED VEH NO : SLA 9271 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS FOO MEI LIAM
ADDRESS : BLK 997B BUANGKOK CRESCENT
#12-863
SINGAPORE 532997
TELEPHONE : HP +65 92315486
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5118056175-01
VEHICLE NO : **SMR 8345 D**
MODEL CODE : AUDI A6 1.8 TFSI ULTRA
MODEL YEAR : 21/5/2018
ENGINE NO : CYG 024727
CHASSIS NO : WAUZZZ4G2JN058900
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Sep-21
PLACE OF ACCIDENT : BLK 105 MULTI-STOREY CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8345 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 1,600.00	500
4	TO REPSRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	550
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR.	S/N \$ 480.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8345 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rep</i>	1	\$ 3,268.00	+
2	FRONT BUMPER FIXING PARTS	1	\$ 543.00	+
3	FRONT BUMPER ADAPTER - LH <i>green</i>	1	\$ 38.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>green</i>	1	\$ 219.00	+
5	FRONT BUMPER AIR GRILLE - LH <i>lit</i>	1	\$ 572.00	✓
6	FRONT BUMPER AIR GRILLE COVER - LH	1	\$ 51.00	+
7	FRONT BUMPER WHEEL SPOILER - LH	1	\$ 264.00	+
8	FRONT BUMPER GUIDE PIECE - LH	1	\$ 38.00	+
9	FRONT PARKING AID SENSOR	1	TBC	+
10	FRONT PARKING AID SENSOR SEAL RING	4	\$ 6.00	+
11	HEADLIGHT MOUNTING - LH	1	\$ 118.00	+
12	HEADLIGHT - LH	1	\$ 9,540.00	+
13	HEADLIGHT LIFT CYLINDER - LH	1	\$ 236.00	+
14	FRONT FENDER STONE GUARD FILM - LH	1	\$ 121.00	+
15	FRONT BUMPER RADAR SENSOR COVER - LH	1	\$ 13.00	+
16	FRONT WHEEL HOUSING LINER - LH	1	\$ 275.00	+
17	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>keep</i>	1	\$ 73.00	+
18	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS			: \$ 15,675.00	
TOTAL LABOUR CHARGES			: \$ 5,152.00	
GRAND TOTAL			: \$ 20,827.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *04/10/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *are Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT