

TP Chaa.
Asher

SLD2656 G.

Toyota Estim.

2362 cc

ACR500192964

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Reer Number Plate	Dehnd	30(SN)	✓
Reer Number Plate Holder	Dehnd	30(SN)	✓
Reer Number Plate Lamp x 02	NP	58 x 2 = 116.	X
Reer Bumper	Distorted	782	✓
Reer Bumper Clips.	Ncr	30(SN)	✓
Reer Bumper Side Holder x 02	Dehnd	96.1 x 2 = 192.20	✓
Reer Bumper Tow Cover x 02	LH Missing	47 x 2 = 94	47.
Reer Bumper Reflector x 02	LH	67.1 x 2 = 134.20	67.10
Reverse Sensor	Dehnd	350(SN)	200(SN)
Reer End Panel.	Distorted	653.10	✓
Reer End Panel Top Garnish.	Deformed	249.10	✓
Reer End Panel Lower Garnish		126.80	✓
Reer End Panel Garnish Clips	Ncr	20(SN)	✓
Reer End Panel Sealant.		60(SN)	✓
Reer End Panel Antenna Sensor	Dehnd	156.90	✓
Taillamp x 02	NP	327.1 x 2 = 654.20	X.

SLD2656G.

Tailgate Distorted	1380	✓
Tailgate Lock Dargd	490	✓
Tailgate Weathershipe. ut	311.70	✓
Tailgate Centre Lamp ^{HP} _{ME}	281.20.	X
Tailgate Side Lamp x 02	Could 266x2=532	✓
Tailgate Inner Trim Board	Could 695	✓
Tailgate Inner Trim Board clips	30(SN)	✓
Tailgate Auto Damper x 02	and 389x2=778	✓
Tailgate Auto Damper Sensor x 02	ME 394x2=788.	X
Tailgate Auto Lock Motor	ME 564	X
Tailgate G(ass) Moulding ?	118.50	✓
Tailgate G(ass) Sealant.	60(SN)	✓
Toyota Logo	Nec 61.90	✓
Estim Wording.	59.80	✓
Aeras Wording.	58.90	✓
Reer Fender Inner Trim Board x 02	Delomel 627.8x2=1255.60	✓
Reer Fender Inner Trim Board clips	ME 60(SN)	✓

SLD26566.

Floor Panel Surround Trim ^{HP} ~~NR~~ 556 X

Floor Panel Surround Trim caps. ^{HP} ~~NR~~ 50(SN) X

Floor Panel Top Foldable Board. ^{del} 687.20

Rear Exhaust Pipe. ^{HP} ~~NR~~ 1081.40 X

Rear Exhaust Pipe Mounting. ^{HP} ~~NR~~ 38.90 X

Rear Camera ^{Damaged} ~~480(SN)~~ 380(SN)
8702.80 S.N. 900
6527.10

Panel Beating
Spray Painting.
Wiring.

To remove reuse sensor.

To remove rear camera.

To remove upholstery.

To spray tuff coat

To remove tailgate glass

To transfer tailgate fittings.

To remove auto tailgate dampers.

To remove exhaust pipe.

~~1200~~ 900

~~1200~~ 900

~~50~~ 30

~~100~~ 50

~~100~~ 50

~~150~~ 80

~~150~~ 60

~~180~~ 120

~~150~~ 80

~~150~~ 50

~~150~~ X.

total: 9747.10

h/s: 7.8K.

07 Days

7.8K