

Not Notation

Recovery B4 paint

4932.80

AAD2109-112

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7956R**

27 SEP 2021

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHB7956R**

JTDKB3FU303083033

TOYOTA

PRIUS

24/09/2021

AGG.

30/08/2019

| PART |                                               | LIST |            |
|------|-----------------------------------------------|------|------------|
| 1    | PANEL SUB-ASSY, FRONT DOOR, LH                | \$   | 1,300.70 ✓ |
| 1    | FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH | \$   | 193.50 X   |
| 1    | HANDLE ASSY, FRONT DOOR OUTSIDE, LH           | \$   | 390.60 X   |
| 1    | WEATHERSTRIP, FRONT DOOR, LH                  | \$   | 231.30 X   |
| 1    | HINGE ASSY, FRONT DOOR, LOWER LH              | \$   | 110.60 X   |
| 1    | HINGE ASSY, FRONT DOOR, UPPER LH              | \$   | 97.50 X    |
| 1    | TAPE, BLACK OUT, NO.1 FRT LH                  | \$   | 13.30 ✓    |
| 1    | TAPE, BLACK OUT, NO.2 FRT LH                  | \$   | 43.50 ✓    |
| 1    | TAPE, BLACK OUT, NO.3 FRT LH                  | \$   | 26.30 ✓    |
| 1    | MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH    | \$   | 926.00 X   |
| 1    | REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH     | \$   | 238.30 X   |
| 1    | MOULDING ASSY, BODY ROCKER PANEL, LH          | \$   | 594.80 ✓   |
| 1    | PANEL SUB-ASSY, QUARTER, LH                   | \$   | 871.50 X   |
| 1    | RETAINER, REAR BUMPER SIDE, LH                | \$   | 116.50 X   |
| 1    | FENDER SUB-ASSY, FRONT LH                     | \$   | 977.80 ✓   |
| 1    | LINER, FRONT FENDER, LH                       | \$   | 202.50 X   |
| 1    | EMBLEM, SIDE PANEL                            | \$   | 54.60 ✓    |

|       |    |          |
|-------|----|----------|
| TOTAL | \$ | 6,389.30 |
| 25%   | \$ | 1,597.33 |
|       | \$ | 4,791.98 |

**Special Nett**

|      |                        |    |         |
|------|------------------------|----|---------|
| 1    | FENDER CLIP            | \$ | 65.00 X |
| 1    | FENDER LINDER CLIP     | \$ | 65.00 X |
| 1SET | DOOR WEATHERSTRIP CLIP | \$ | 65.00 X |

7301-19  
1392  
1132.41  
5928.82

1808-22



**Trans-cab Auto Services Pte Ltd**

AAD2109-112

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7956R**

- 1 FRT DOOR STICKER TRANSCAB  
1 TYRE  
1 RIM *pr*  
1SET CLIP, ROCKER PANEL MOULDING  
**TOTAL**

\$ *nn* 100.00 *born*  
\$ *nn* 350.00 *X*  
\$ *nn* 1,879.40 *✓*  
\$ *nn* 65.00 *✓*  
**\$ 2,589.40**

**TOTAL PARTS \$ 7,381.38**

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,000.00 *400h*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *660h*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *60h*

To Check Electrical Lighting Concerned.

\$ 170.00 *20h*

**TOTAL \$ 4,190.00**

**Over All Total \$ 11,571.38**

**(PART-BY-PART) Repair Days**

*20 days*

*3 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: