

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH7777D

Make : HYUNDAI

Model : IONIQ(G3)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 27/09/2021

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Acknowledged by Repairer	Type	Unit Price	Amount
1	FRT BUMPER COVER / CPA	Signature:			\$430.90
10	FRT BUMPER CLIPS / MCL	Date:			\$22.00
1	FRT BUMPER LOWER GRILLE MOULDING / RL				\$127.60
1	HEADLAMP LH RH / CPA ?			\$1,993.65	\$3,987.30
2	HEADLAMP SUPPORT PANEL				\$949.30
1	RADIATOR GRILLE / CPA				\$1,409.10
1	FRT BUMPER MOULDING CENTRE UPP ?				\$368.50
1	FRT BUMPER SPONGE ?				\$186.90
1	FRT BUMPER REINFORCEMENT ?				\$1,075.10
2	FRT BUMPER REINFORCEMENT ABSORBER LH RH ?			\$186.50	\$373.00
1	FRT BUMPER MOULDING CENTRE UPPER ?				\$368.50
1	FRT BUMPER TOWING COVER X NW ?				\$29.00
1	FRT BUMPER LOWER STIFFNER ?				\$285.10
1	EMBLEM H / MCL				\$31.30
2	FRT BUMPER TOP BRACKET LH RH ?			\$35.00	\$70.00
2	FRT BUMPER BRACKET LH RH ?			\$28.00	\$56.00
2	FRT BUMPER AIR DUCT LH RH ?			\$76.90	\$153.80
1	RADIATOR ?				\$710.50
1	RADIATOR INVERTER ?				\$884.80
1	COOLANT ?				\$45.00
1	AIRCON CONDENSER ?				\$663.60
2	ANTENNA ASSY SMARTKEY LH RH ?			\$80.20	\$160.40
1	COVER ASSY SCCC UNIT ?				\$767.30
SUB TOTAL					\$13,155.00
LESS 20%					\$2,631.00
DISCOUNTED TOTAL					\$10,524.00
FRT NUMBER PLATE WITH TRIM COVER / mis					\$55.00
					\$55.00
Labour Charge					
PANEL BEATING					\$1,100.00
SPRAY PAINTING CHARGE					\$300.00
TOWING FEE					\$60.00
REMOVE/ REFIX RADIATOR					\$90.00
CHECK ALL LIGHTING					\$80.00
TOTAL LABOUR					\$1,630.00
ESTIMATE TOTAL					\$12,209.00

nett

350  
250  
-  
?  
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

One Qiang 4:39pm  
27/9/21