



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/000

LKK

TP Somp
Xiao Chun

KPH2230029053

DATE: 02/12/2021 OUR REF: UAPL1500
REPAIR ESTIMATE YOU THE TOYOTA HIROOF NO: PC5645B

- 1 FRONT BONNET ASSY *Refr*
- 1 FRONT BONNET HINGES *Refr*
- 1 FRONT BUMPER FACE *Deformed*
- 1 FRONT BUMPER TOP BRACKET *Refr*
- 1 FRONT BUMPER LOWER REFORCIMENT *new*
- 1 FRONT BUMPER CENTRE LOWER GRILLE *lt.*
- 1 FRONT BUMPER R/H FOG LAMP *new*
- 1 FRONT BUMPER R/H FOG LAMP COVER *lt.*
- 1 FRONT BUMPER L/H SIDE RETAINER *Deformed*
- 1 SET FRONT BUMPER CLIPS *new*
- 1 FRONT RADIATOR GRILLE ASSY *cracked*
- 1 FRONT R/H CORNER PANEL *Distorted*
- 1 FRONT AIR CLEANER HOUSING TOP JOINT GARNISH *new*
- 1 FRONT AIR CLEANER HOUSING *cracked*
- 1 FRONT AIR CLEARING SENSOR *new*
- 1 FRONT R/H HEADLAMP ASSY *cracked*
- 1 FRONT R/H HEADLAMP SIDE HOLDER *cracked*
- 1 FRONT R/H STEP PANEL ASSY *3 new*
- 1 FRONT R/H STEP PANEL GARNISH
- 1 FRONT R/H CABLE SOCKET HOLDER *cracked*
- 1 FRONT R/H SIDE CENTRE PANEL *Refr*
- 1 FRONT R/H DOOR PILLAR PANEL (OUTER) *Refr*
- 1 FRONT R/H DOOR ASSY *Refr*

LESS 25 %.....

\$	913.60	x
\$	118.00	x
\$	856.20	594
\$	277.80	x
\$	487.60	x
\$	255.80	198
\$	280.10	x
\$	89.90	✓
\$	193.10	97
\$	55.00	30
\$	778.00	580
\$	212.40	✓
\$	178.60	+
\$	1,012.20	780
\$	412.20	x
\$	2,458.00	2201
\$	75.00	✓
\$	155.60	x
\$	155.60	x
\$	115.20	✓
\$	458.20	x
\$	771.20	x
\$	1,794.00	x
\$	12,103.90	
\$	3,025.98	
\$	<u>9,077.93</u>	

4972.50

3729.37

SPECIAL NETT:

- 1 FRONT BUMPER LOWER SPOILER *Deformed*
- 1 FRONT HEADLAMP OUTER BLACK COVER *cracked*
- 1 FRONT R/H CORNER PANEL OUTER BLACK COVER *cracked*

620

\$	500.00	380
\$	150.00	120
\$	150.00	120

LABOUR CHARGES:-

TO DISM/REWIRE DAMAGED SOCKET HOLDER, DOOR WIRING.

TO SPARY UNDERCOATING IN REPAIR

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

TO PUTTY AND RESPRAY DAMAGED PORTION

TO SENT VEHICLE FOR COMPUTER ALIGHTMENT

1080

\$	180.00	30
\$	100.00	50
\$	1,200.00	600
\$	1,100.00	400
\$	120.00	x
\$	<u>12,577.93</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5429.37

W/S: 4.3K

03 Days