



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU) Reg No/Reg Date SLQ8931D / 26/07/201 Date In/Mileage 27/09/2021/ 0 Chassis No JMYSRCY1AGU006859 Engine No 4A92CP5076 Make/Model MIT/16MY LANCER EX 1.6 (F52) Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/09/2021/ 18:55	BLK	282 / Kevin Leong	15881
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	1 1 2 1 1/2				6750.00
REPLACE FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER,		5 1/2 x 450			2475
FRT LH BODY CHASSIS & AFFECTED AREA					
REPAIR ON FRT RH BODY CHASSIS, FRT LH WHEEL HOUSING					
E PNT98000	1 1 1 2				2800.00
PAINT WORK ON FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER,		6 x 350			2100
BOTH FRT BODY CHASSIS & FRT LH DOOR					
E PNT88000					120.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR		(photo)			
A 55900099					80.00
TO TOP UP AIRCON GAS					
A 11900199					450.00
REMOVE & INSTALL ENGINE ASSY FOR FACILITATE REPAIR					
M SUNDRY					150.00
TO APPLY SEALANT ON AFFECTED AREA					
M SUNDRY					160.00
PERFORM RUST PREVENTION					
A 54900099					30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					
A 10028901					120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					
M SUNDRY					50.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME					
B WHEELALIGNMENT					120.00
To Conduct Computerize Full Wheel Alignment					
M SUNDRY					50.00
SUNDRIES					
E PNT88100					1000.00
TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT					
M HEADLAMP ASSY,LH	BR	1.00	851.00	23.00	655.27
M HEADLAMP ASSY,RH	BR	1.00	851.00	23.00	655.27
M TANK,WINDSHIELD WASHER	? - BR	1.00	91.00	23.00	70.07
M HORN	? X M	1.00	89.00	23.00	68.53

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<tr> <td>Cust No/Name</td><td>KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLQ89310 / 26/07/201</td></tr> <tr> <td>Date In/Mileage</td><td>27/09/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>JMYSRCY1AGU006859</td></tr> <tr> <td>Engine No</td><td>4A92CP5076</td></tr> <tr> <td>Make/Model</td><td>MIT/16MY LANCER EX 1.6 (F52)</td></tr> <tr> <td>Colour/Trim</td><td>DOO LIGHTNING BLUE / BK BLACK</td></tr>	Cust No/Name	KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU)	Reg No/Reg Date	SLQ89310 / 26/07/201	Date In/Mileage	27/09/2021/ 0	Chassis No	JMYSRCY1AGU006859	Engine No	4A92CP5076	Make/Model	MIT/16MY LANCER EX 1.6 (F52)	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK
Cust No/Name	KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU)														
Reg No/Reg Date	SLQ89310 / 26/07/201														
Date In/Mileage	27/09/2021/ 0														
Chassis No	JMYSRCY1AGU006859														
Engine No	4A92CP5076														
Make/Model	MIT/16MY LANCER EX 1.6 (F52)														
Colour/Trim	DOO LIGHTNING BLUE / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/09/2021/ 18:55	BLK	282 / Kevin Leong	15881
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CONDENSER ASSY, A/C REFRIGE	? x nn	1.00	1140.00	23.00	877.80
M RADIATOR ASSY	? x nn	1.00	1130.00	23.00	870.10
M SHROUD, COOLING FAN	? x nn	1.00	259.00	23.00	199.43
M MOTOR, COOLING FAN(*)	? x nn	1.00	472.00	23.00	363.44
M FAN, COOLING	? x nn	1.00	75.00	23.00	57.75
M TANK ASSY, RADIATOR COND	X nn	1.00	60.00	23.00	46.20
M BRACKET, ENG FR MOUNTING	? x nn	1.00	195.00	23.00	150.15
M BRKT, ENG RR ROLL STOPPER	? x nn	1.00	114.00	23.00	87.78
M BRACKET, ROLL STOPPER	? - BT	1.00	122.00	23.00	93.94
M BRACKET, T/M MOUNTING	? x nn	1.00	163.00	23.00	125.51
M CLIP, FLOOR TRIM	? x nn	2.00	4.00	23.00	6.16
M DUCT, A/CLNR INTAKE	? x nn	1.00	163.00	23.00	125.51
M BOLT, FUEL TANK	? x nn	2.00	2.00	23.00	3.08
M COVER, HEADLAMP SUPT PANEL	? x nn	1.00	70.00	23.00	53.90
M BRACKET, FR BUMPER SIDE, LH	? - CR	1.00	17.00	23.00	13.09
M BRACKET, FR BUMPER SIDE, RH	? - CR	1.00	17.00	23.00	13.09
M COVER, FR BUMPER	? - CR	1.00	38.00	23.00	29.26
M COVER, FR BUMPER GRILLE	? - mis	1.00	5.00	23.00	3.85
M COVER, FR BUMPER GRILLE	? - cut	1.00	5.00	23.00	3.85
M REINFORCEMENT, FR BUMPER	? - BT	1.00	93.00	23.00	71.61
M FACE, FR BUMPER	? - CR	1.00	1045.00	23.00	804.65
M GARNISH, FR BUMPER, LH	? x nn	1.00	30.00	23.00	23.10
M GARNISH, FR BUMPER, RH	? - mis	1.00	30.00	23.00	23.10
M GRILLE, RADIATOR	? - CR	1.00	270.00	23.00	207.90
M MARK, THREE-DIA	? - mis	1.00	70.00	23.00	53.90
M GRILLE, FR BUMPER	? - CR	1.00	78.00	23.00	60.06
M CLIP, FR BUMPER	? - nrc	10.00	3.00	23.00	23.10
M REINFORCEMENT, FR BUMPER	? - BT (photo)	1.00	531.00	23.00	408.87
M WEATHERSTRIP, HOOD, FR	? x nn	1.00	31.00	23.00	23.87
M WEATHERSTRIP, HOOD	? x nn	1.00	18.00	23.00	13.86
M HINGE, HOOD, LH	? - BT	1.00	64.00	23.00	49.28
M HINGE, HOOD, RH	? - BT	1.00	64.00	23.00	49.28
M INSULATOR, HOOD	? x nn	1.00	95.00	23.00	73.15

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU) Reg No/Reg Date SLQ8931D / 26/07/201 Date In/Mileage 27/09/2021/ 0 Chassis No JMYSRCY1AGU006859 Engine No 4A92CP5076 Make/Model MIT/16MY LANCER EX 1.6 (F52) Colour/Trim D00 LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/09/2021/ 18:55	BLK	282 / Kevin Leong	15881			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LATCH,HOOD	- BT			1.00	58.00	23.00	44.66
M	FENDER,FR LH	- 00			1.00	622.00	23.00	478.94
M	FENDER,FR RH	- 00			1.00	622.00	23.00	478.94
M	BRACKET,FR FENDER,RH	- BR			1.00	16.00	23.00	12.32
M	BRACKET,FR FENDER,LH	x nn			1.00	16.00	23.00	12.32
M	PANEL,HEADLAMP SUPPORT,LWR	- BT			1.00	511.00	23.00	393.47
M	EXTENSION,FR SIDEMEMBER,RH	x nn			1.00	41.00	23.00	31.57
M	EXTENSION,FR SIDEMEMBER,LH	x nn			1.00	41.00	23.00	31.57
M	PNL,HEADLAMP SUPT,UPR LH	BT			1.00	86.00	23.00	66.22
M	PNL,HEADLAMP SUPT,UPR RH	BT			1.00	86.00	23.00	66.22
M	PANEL,HEADLAMP SUPPORT,UPR	BT			1.00	297.00	23.00	228.69
M	COVER,ENG ROOM UNDER,FR	x nn			1.00	141.00	23.00	108.57
M	SHIELD,FR FENDER,FR LH	x nn			1.00	119.00	23.00	91.63
M	SHIELD,FR FENDER,FR RH	x nn			1.00	119.00	23.00	91.63
M	COVER,FR DECK GARNISH,LH	x nn			1.00	23.00	23.00	17.71
M	COVER,FR DECK,LH	x nn			1.00	9.00	23.00	6.93
M	GARNISH,FR FENDER	x nn			2.00	65.00	23.00	100.10

Steve (LKK)
29/9/21, 11:00am

00- M1 AL
Excess - ?
PIP

M Bel Sm

18 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett 20,600.25
7% GST on 20600.25 1442.02
Total Payable 22,042.27

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.