



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU)
	Reg No/Reg Date	SLQ8931D / 26/07/201
	Date In/Mileage	27/09/2021/ 0
	Chassis No	JMYSRCY1AGU006859
	Engine No	4A92CP5076
	Make/Model	MIT/16MY LANCER EX 1.6 (F52)
	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/09/2021/ 18:55	BLK	282 / Kevin Leong	15881			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER, FRT LH BODY CHASSIS & AFFECTED AREA REPAIR ON FRT RH BODY CHASSIS, FRT LH WHEEL HOUSING								6750.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER, BOTH FRT BODY CHASSIS & FRT LH DOOR								2800.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								120.00
A 55900099 TO TOP UP AIRCON GAS								80.00
A 11900199 REMOVE & INSTALL ENGINE ASSY FOR FACILITATE REPAIR								450.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA								150.00
M SUNDRY PERFORM RUST PREVENTION								160.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME								50.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY SUNDRIES								50.00
E PNT88100 TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT								1000.00
M HEADLAMP ASSY,LH					1.00	851.00	23.00	655.27
M HEADLAMP ASSY,RH					1.00	851.00	23.00	655.27
M TANK,WINDSHIELD WASHER					1.00	91.00	23.00	70.07
M HORN					1.00	89.00	23.00	68.53

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU)
	Reg No/Reg Date	SLQ8931D / 26/07/201
	Date In/Mileage	27/09/2021/ 0
	Chassis No	JMYSRCY1AGU006859
	Engine No	4A92CP5076
	Make/Model	MIT/16MY LANCER EX 1.6 (F52)
	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/09/2021/ 18:55	BLK	282 / Kevin Leong	15881
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CONDENSER ASSY,A/C REFRIGE		1.00	1140.00	23.00	877.80
M RADIATOR ASSY		1.00	1130.00	23.00	870.10
M SHROUD,COOLING FAN		1.00	259.00	23.00	199.43
M MOTOR,COOLING FAN(*)		1.00	472.00	23.00	363.44
M FAN,COOLING		1.00	75.00	23.00	57.75
M TANK ASSY,RADIATOR COND		1.00	60.00	23.00	46.20
M BRACKET,ENG FR MOUNTING		1.00	195.00	23.00	150.15
M BRKT,ENG RR ROLL STOPPER		1.00	114.00	23.00	87.78
M BRACKET,ROLL STOPPER		1.00	122.00	23.00	93.94
M BRACKET,T/M MOUNTING		1.00	163.00	23.00	125.51
M CLIP,FLOOR TRIM		2.00	4.00	23.00	6.16
M DUCT,A/CLNR INTAKE		1.00	163.00	23.00	125.51
M BOLT,FUEL TANK		2.00	2.00	23.00	3.08
M COVER,HEADLAMP SUPT PANEL		1.00	70.00	23.00	53.90
M BRACKET,FR BUMPER SIDE,LH		1.00	17.00	23.00	13.09
M BRACKET,FR BUMPER SIDE,RH		1.00	17.00	23.00	13.09
M COVER,FR BUMPER		1.00	38.00	23.00	29.26
M COVER,FR BUMPER GRILLE		1.00	5.00	23.00	3.85
M COVER,FR BUMPER GRILLE		1.00	5.00	23.00	3.85
M REINFORCEMENT,FR BUMPER		1.00	93.00	23.00	71.61
M FACE,FR BUMPER		1.00	1045.00	23.00	804.65
M GARNISH,FR BUMPER,LH		1.00	30.00	23.00	23.10
M GARNISH,FR BUMPER,RH		1.00	30.00	23.00	23.10
M GRILLE,RADIATOR		1.00	270.00	23.00	207.90
M MARK,THREE-DIA		1.00	70.00	23.00	53.90
M GRILLE,FR BUMPER		1.00	78.00	23.00	60.06
M CLIP,FR BUMPER		10.00	3.00	23.00	23.10
M REINFORCEMENT,FR BUMPER		1.00	531.00	23.00	408.87
M WEATHERSTRIP,HOOD,FR		1.00	31.00	23.00	23.87
M WEATHERSTRIP,HOOD		1.00	18.00	23.00	13.86
M HINGE,HOOD,LH		1.00	64.00	23.00	49.28
M HINGE,HOOD,RH		1.00	64.00	23.00	49.28
M INSULATOR,HOOD		1.00	95.00	23.00	73.15

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU)
	Reg No/Reg Date	SLQ8931D / 26/07/201
	Date In/Mileage	27/09/2021/ 0
	Chassis No	JMYSRCY1AGU006859
	Engine No	4A92CP5076
	Make/Model	MIT/16MY LANCER EX 1.6 (F52)
	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/09/2021/ 18:55	BLK	282 / Kevin Leong	15881
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LATCH,HOOD		1.00	58.00	23.00	44.66
M FENDER,FR LH		1.00	622.00	23.00	478.94
M FENDER,FR RH		1.00	622.00	23.00	478.94
M BRACKET,FR FENDER,RH		1.00	16.00	23.00	12.32
M BRACKET,FR FENDER,LH		1.00	16.00	23.00	12.32
M PANEL,HEADLAMP SUPPORT,LWR		1.00	511.00	23.00	393.47
M EXTENSION,FR SIDEMEMBER,RH		1.00	41.00	23.00	31.57
M EXTENSION,FR SIDEMEMBER,LH		1.00	41.00	23.00	31.57
M PNL,HEADLAMP SUPT,UPR LH		1.00	86.00	23.00	66.22
M PNL,HEADLAMP SUPT,UPR RH		1.00	86.00	23.00	66.22
M PANEL,HEADLAMP SUPPORT,UPR		1.00	297.00	23.00	228.69
M COVER,ENG ROOM UNDER,FR		1.00	141.00	23.00	108.57
M SHIELD,FR FENDER,FR LH		1.00	119.00	23.00	91.63
M SHIELD,FR FENDER,FR RH		1.00	119.00	23.00	91.63
M COVER,FR DECK GARNISH,LH		1.00	23.00	23.00	17.71
M COVER,FR DECK,LH		1.00	9.00	23.00	6.93
M GARNISH,FR FENDER		2.00	65.00	23.00	100.10

Confirm & accepted by			
	7% GST on	Nett 20600.25	20,600.25 1442.02
		Total Payable	22,042.27
Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.