

SJR9933K 2016 July.

TP III

Mazda 3 1496cc

Denise.

JM6BM42A8G0342536.

Front Bumper	Deformed	1083.30	/
Front Bumper Clips.	new	30(SN)	/
Front Bumper Side Holder RH.	Damaged	25.20	/
Front Bumper Reinforcement.	new	466.80	X
Front Bumper Fog Lamp RH.	Cracked	351.30	/
Front Bumper Fog Lamp Cover RH.	Cut	110.20	/
Front Bumper Signal Lamp RH	Cracked	165	/
Front Grille Chrome Moulding RH.	Cracked	185.60	/
Headlamp RH	Cut	2357.30	/
Headlamp Lower Bracket RH.			
Front Support Panel	new	469.70	X
Radiator Coolant.	new	50(SN)	X
Front RH Fender	Distorted	392.90	/
Front RH Fender Bracket.	Best	75.90	/

SJR99331C

Front RH Fender Inner Shield	2 x4	129.30 x
Front RH Fender Inner Shield Clips	m	30(SN) x
Front RH Wheel Rim		1337.20 +
Front RH Lower Arm	x4	484.70 +
Front RH Shock Absorber	m	381 x
Front RH Knuckle Arm		384.40 +
Front RH Wheel Hub c/w Bearing		435.80 +
Wiper Washer Tank Deformed		169.30 -
Wiper Washer Tank Motor	x4 m	112.30 +
Headlamp Washer Pump RH. cracked		242.40 -
Front Bumper Sensor RH.	x4 m	218 x.

5188.40

4126.72

SJR9933K.

Panel Beating.

~~1400~~ 600

Spray Painting.

~~800~~ 400

Wiring

~~50~~ 30

To spray tuff coat

~~150~~ 40

To remove condenser and
to top up air con gas }

120 x

To remove radiator and
to top up coolant }

120 x

To remove undercarriage

350 x

To perform wheel alignment.

150 x.

1070

13870.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5196.72

L/S: 4150

04 Days.