

ASS. REC BY:

REF:

C22/ 2101 0083/KU

Kenaeth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNB 5941A Yr Regn: 08, 21Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Tesla Model 3 c.c. _____Colour: M-P White A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LRW31F7ELX MC 26325Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: _____ R: 235/35R20BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 28/9/21

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 28/9/2021

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt MS & Rrt O/S

The UIC / Chassis frame / Body Structure affected due to collision. ✓

Date / Time Action / Instruction

/ Unable to open the door, set video

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Date: 27.09.2021
Vehicle No: SNB5941A
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7ELXMC263525
Reg. Year: 2021

Not Notified
Penalty 64 points
10 days

Third Party Insurer: CHN TAIPING
Third Party Veh No: SKC2830L
Date of Accident: 24.09.2021
Estimator: VICTOR
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>APL</i> \$950.00
2	FRONT BUMPER SIDE BRACKET LH	1		<i>CM</i> \$35.00
3	FRONT BUMPER SIDE BRACKET RH	1		<i>DI</i> \$35.00
4	FRONT BUMPER RETAINER LH	1		<i>CM</i> \$20.00
5	FRONT BUMPER RETAINER RH	1		<i>DI</i> \$20.00
6	FRONT SUPPORT PANEL	1		<i>CM</i> \$1,210.00
7	FRONT SUPPORT TOP BRACKET LH	1		<i>R</i> \$35.00
8	FRONT SUPPORT TOP BRACKET RH	1		\$35.00
9	FRONT TOW COVER	1		<i>Sn</i> \$45.00
10	FRONT LOWER GRILLE	1		\$190.00
11	FRONT REINFORCEMENT BEAM	1		\$405.00
12	FRONT BEAM FOAM	1		<i>CM</i> \$90.00
13	FRONT ANKLE CATCHER	1		\$185.00
14	FRONT REINFORCEMENT CRASH CAN LH	1		\$80.00
15	FRONT FENDER LH	1		<i>R</i> \$850.00
16	FRONT UPPER RAIL OUTER LH	1		\$250.00
17	FRONT UPPER RAIL INNER LH	1		\$250.00
18	SHOCK TOWER UPPER LH	1		\$300.00
19	FRONT LOWER RAIL LH	1		\$160.00
20	FRONT RAIL OUTER LH	1		\$900.00
21	FRONT RAIL INNER REINFORCEMENT LH	1		\$120.00
22	FRONT WHEEL LINER LH	1		<i>CM</i> \$220.00
23	FRONT FENDER RH	1		<i>Bu</i> \$850.00
24	FRONT WHEEL LINER RH	1		<i>DI</i> \$220.00
25	FRONT WINDSCREEN	1		<i>CM</i> \$1,140.00
26	FRONT HOOD	1		<i>R</i> \$1,300.00
27	FRONT HOOD HINGE LH	1		<i>DI</i> \$120.00
28	FRONT HOOD HINGE RH	1		<i>DI</i> \$120.00
29	FRONT HOOD HINGE COVER LH	1		<i>MI</i> \$15.00
30	FRONT HOOD HINGE COVER RH	1		<i>MI</i> \$15.00
31	FRONT HOOD STRUT LH	1		<i>Sn</i> \$105.00
32	FRONT HOOD STRUT RH	1		<i>Sn</i> \$105.00
33	FRONT HOOD STRUT BRACKET LH	1		\$30.00
34	FRONT HOOD STRUT BRACKET RH	1		\$30.00
35	FRONT DOOR LH	1		<i>R</i> \$1,890.00
36	FRONT DOOR UPPER HINGE LH	1		<i>R</i> \$150.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 27.09.2021
Vehicle No: SNB5941A
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7ELXMC263525
Reg. Year: 2021

Third Party Insurer: CHN TAIPING
Third Party Veh No: SKC2830L
Date of Accident: 24.09.2021
Estimator: VICTOR
Surveyor:

37	FRONT DOOR UPPER HINGE RH	1		R	\$150.00	X
38	SHOCK TOWER COVER LH	1			\$55.00	?
39	SHOCK TOWER COVER RH	1			\$55.00	?
40	FRONT UNDERHOOD COWLING	1			\$140.00	?
41	FRONT UNDERHOOD APRON ASSY	1			\$180.00	?
42	FRONT UNDER COVER	1		CM	\$365.00	✓
43	FRONT TESLA EMBLEM	1		na	\$85.00	✓
44	FRONT LUGGAGE COMPARTMENT	1		Return	\$580.00	✓
45	HEADLAMP LH	1		Pro	\$2,250.00	✓
46	HEADLAMP RH	1		my Pro	\$2,250.00	✓
47	HEADLAMP BRACKET LH	1		Ry	\$45.00	✓
48	HEADLAMP BRACKET RH	1			\$45.00	?
49	FRONT PARKING SENSORS	Shay 2	\$290.00		\$1,740.00	LIT
50	FRONT PARKING SENSORS BRACKET	6	\$15.00		\$90.00	?
51	FRONT RADAR SENSOR	1			\$640.00	?
52	FRONT HORN ASSY	1			\$275.00	?
53	FRONT SUBFRAME	1			\$2,470.00	?
54	FRONT KNUCKLE ARM LH	1		Ry	\$780.00	✓
55	FRONT WHEEL BEARING LH	1		na	\$290.00	✓
56	FRONT LOWER CONTROL ARM LH	1			\$375.00	?
57	FRONT LATERAL LOWER LINK LH	1			\$390.00	?
58	FRONT UPPER ARM LH	1			\$240.00	?
59	FRONT STABILIZER BAR	1			\$420.00	?
60	FRONT STABILIZER LINK	1			\$50.00	?
61	FRONT TIE ROD LH	1			\$240.00	?
62	FRONT TIE ROD RH	1			\$240.00	?
63	FRONT WHEEL LH	1		na	\$1,790.00	✓
64	FRONT WHEEL RH	1		na	\$1,790.00	✓
65	FRONT TYRE 235/30/R20	2	\$650.00		\$1,300.00	Return
				PARTS TOTAL	\$31,795.00	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	na	\$150.00
2	FRONT LOWER GRILLE CLIPS			\$80.00
3	BONNET INSULATOR CLIPS		na	\$70.00
4	FRONT COWLING LH/RH CLIPS		na	\$120.00
5	FRONT UNDERHOOD COWLING CLIPS		na	\$70.00

Head office
8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 27.09.2021
Vehicle No: SNB5941A
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7ELXMC263525
Reg.Year: 2021

Third Party Insurer: CHN TAIPING
Third Party Veh No: SKC2830L
Date of Accident: 24.09.2021
Estimator: VICTOR
Surveyor:

6	FRONT UNDERHOOD APRON ASSY CLIPS			1ea	\$70.00	✓
7	FRONT UNDER COVER CLIPS				\$100.00	✓
8	SHOCK TOWER COVER LH/RH CLIPS				\$80.00	✓
9	FRONT WINDSCREEN SEALANT			1ea	\$120.00	405N
S/N TOTAL					\$860.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST FRT ACCIDENT AREA.	\$1,400.00	8001
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.	\$2,000.00	19006
LABOUR CHARGES TO DISMANTLE AND RE-INSTALL UNDERCARRIAGE.	\$300.00	2001
TO CONDUCT WHEEL ALIGNMENT.	\$100.00	601
TO REMOVE AND INSTALL FRONT WINDSCREEN	\$250.00	1201
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$200.00	801
TO DIAGNOSE FAULT CODE & RESET MEMORY.	\$400.00	?
TOWING BILL CHARGES (FLATBED)	\$150.00	1201

LABOUR TOTAL \$4,800.00

TOTAL \$36,595.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Branch (Motor Insurance Claims)

Head office

8 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

810 Ang Mo Kio Road Singapore 560047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please don't gloss over the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder, and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any loss resulting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and this copies of this report will, for a fee, be made available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/09/2021 12:32 (SGT)
Date of Accident	24/09/2021 21:44 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TPE (NEAR SELETAR LINK EXIT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB5941A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KUANG JINGHAO
NRIC No	SXXXX595I
Email Address	DAMNSHIOK@GMAIL.COM
Mobile Phone No	(Phone) +65-92392880
Alternative Phone No	+65-92392880

VEHICLE PARTICULARS

Manufacturer	Tesla
Model	MODEL 3 PERFORMANCE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1599


INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	CN140349
Cover Note Number	25/08/2021 - 24/08/2022

DRIVER

Name of Driver	KUANG JINGHAO
NRIC No	SXXXX595I

Date of accident: 24/09/2021 Time: 21:44 Location: TPE (NEAR SELETAR UNK EXIT)
 My Vehicle A: SNB5941A Vehicle B: SKC 2830C Vehicle C: BARRICADE
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER to POLICE REPORT = T/20210925/7004

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: OPTIMA WERKZ PTE LTD

Email address: eve.tan@ow.sg

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

12
Policyholder's Signature

Date & Time:

25/09/2021

Driver's Signature

(if driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

AH LIM MOTOR COMPANY