

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Model : ISUZU NMR

Accident Date : 22.09.2021

Original Reg Date : 28.12.2016

Chassis : JAANMR85HF7103195

TP Ins. AIG

Veh No: YP4959C

ESTIMATE

1	1 pc	Front Corner Panel RH <i>Dehid</i>		285.90	✓
2	1 pc	Headlamp RH <i>Not new</i>		427.00	X
3	1 set	Headlamp Clips <i>not new</i>		30.00	+
4	1 pc	Headlamp Bottom Rubber LH <i>new</i>		36.00	+
5	1 pc	Front Signal Lamp RH <i>new</i>		245.30	+
6	1 set	Front Signal Lamp clips		30.00	+
7	1 pc	Front Grille <i>new</i>		421.00	+
8	1 set	Front Grille Clips		30.00	+
9	1 pc	Front Bumper <i>new</i>		596.00	+
10	1 pc	Front Bumper Side Bracket		97.00	+
11	1 pc	Front door Rh <i>Dehid</i>		987.50	✓
12	1 pc	Front door signal lamp Rh <i>new</i>		109.60	+
13	1 pc	Front door inner trim Rh		598.30	+
14	1 pc	Front door weatherstrip Rh		198.60	+
15	2 pc	Front door hinges Rh	78.90	157.80	+
16	1 pc	Front door checker Rh		89.50	+
17	1 pc	Front door lower arch garnish Rh		198.20	+
18	1 pc	Front step panel garnish reflector Rh		65.30	+
19	1 pc	Front step panel garnish Rh		185.90	+

4,788.90

Less 15%

718.34

4,070.57

Special Nett

1	1 set	Front door company sticker(customized) <i>Nec.</i>		350.00	250
---	-------	--	--	-------------------	-----

Labour charge

Panel Beating		1,000.00	400
Spray painting		1,000.00	300
Check Wiring on headlamp		120.00	30
Anti rust		100.00	X
Remove and transfer door mechanism		120.00	80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total: 2142.39

\$ 6,760.57

H/S: 1.7K

Adrian Li

1/5 28/09/21

03 Days
1.7K