



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company & GST Registration No : 201828067M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Final survey is on a "Without Prejudice" basis
- Legal modification(s) is a lowered
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

VEHICLE INSPECTION ESTIMATE

M/S : AIG Asia Pacific Insurance Pte Ltd
(MOTOR CLAIM DEPARTMENT)

Email aigsgp_claimssurvey@aig.com

Justin.

Parts - (%)	Signature:
SN	Date:
Labour	
Lump sum	
ERV	

Acknowledged by Repairer

Vehicle No: SKP7017S Date: 27.09.2021
Vehicle Model: BMW335I Reg. Date: 09.03.2012
Chassis No: WBA3A92030F095630 D.O.A: 27.09.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Bonnet <i>Dented</i>	1	\$ 1,350.00	\$ 1,350.00	✓
2	Front Bumper Tow Cover <i>New</i>	1	\$ 64.20	\$ 64.20	✓
3	Front Bumper Spray Nozzle RH <i>Dented</i>	1	\$ 194.90	\$ 194.90	✓
4	Front Bumper Spray Nozzle Cover RH <i>Dented</i>	1	\$ 64.80	\$ 64.80	✓
5	Front Bumper Spray Nozzle Water Hose RH <i>New</i>	1	\$ 80.00	\$ 80.00	✓
6	Front Bumper Side Retainer RH <i>Dented</i>	1	\$ 46.00	\$ 46.00	✓
7	Front Bumper Fog Lamp RH <i>Cracked</i>	1	\$ 295.00	\$ 295.00	✓
8	Front Bumper Fog Lamp Cover RH <i>Cracked</i>	1	\$ 90.40	\$ 90.40	✓
9	Front Bumper Air Duct RH <i>Cracked</i>	1	\$ 64.70	\$ 64.70	✓
10	Front Bumper Air Duct Support RH <i>New</i>	1	\$ 68.00	\$ 68.00	✓
11	Headlamp RH <i>Cracked</i>	1	\$ 2,130.60	\$ 2,130.60	✓
12	Headlamp Bottom Retainer RH <i>New</i>	1	\$ 136.00	\$ 136.00	✓
13	Front RH Fender <i>Regis</i>	1	\$ 850.60	\$ 850.60	✓
14	Front RH Fender Inner Cowling RH <i>Torn</i>	1	\$ 175.20	\$ 175.20	✓
15	Bulb Replacement Cover RH <i>Missin</i>	1	\$ 35.60	\$ 35.60	✓
16	Intercooler Air Vent <i>New</i>	1	\$ 135.60	\$ 135.60	✓

Total For List Items: \$ 5,781.60

Less Spare Parts Discount (5%): \$ 289.08

Total: \$ 5,492.52

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Bumper - M Performance <i>Distorted</i>	1	\$ 1,650.00	\$ 1,650.00	✓
4	Front Bumper Clips 1set <i>New</i>	1	\$ 30.00	\$ 30.00	✓
5	Front Grille Clips 1set <i>New</i>	1	\$ 30.00	\$ 30.00	✓
8	Front Fender Top Garnish Clips 1set <i>New</i>	1	\$ 30.00	\$ 30.00	✓

Total For S/N Items: \$ 90.00

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,000.00	\$ 1,000.00	600
2	To respray accident affected areas	1	\$ 1,000.00	\$ 1,000.00	600
3	To tuff coat affected areas	1	\$ 120.00	\$ 120.00	40
4	To conduct wiring check and repair	1	\$ 60.00	\$ 60.00	30
5	To check and realign headlamp and focus	1	\$ 60.00	\$ 60.00	X

Total For Labour: \$ 2,240.00

Grand Total: \$ 7,822.52

4527

4074.30

1680

Adrian Ly

2/9/2021

05 Day

total: 7024.30

R/S: 5.6K.