

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

PAN JUI CHU
BLK 439B SENGKANG WEST AVE #20-317
SINGAPORE 792439

Contact : 96482936, 93884875

TP Chang
Veron

ESTIMATE

Repair Code : CLM15324

Date in : 27/09/2021

Vehicle Num. : SMC3630S

Model : TOYOTA COROLLA ALTIS ELEGANCE AUTO

Chassis/Eng# : MR053REH604584761/1ZR0B77779

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Distohd</i>	1	793.20	✓ 793.20
REAR BOOTLID 'ALTIS' EMBLEM	1	45.60	✓ 45.60
REAR BOOTLID 'COROLLA' EMBLEM	1	41.00	✓ 41.00
REAR BOOTLID 'LOGO' EMBLEM	1	50.70	✓ 50.70
REAR BOOTLID HINGES L/R <i>Best</i>	2	69.90	✓ 139.80
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	30.70	✗ 61.40
REAR BOOTLID INNER TRIM BOARD <i>Delhd</i>	1	267.00	✓ 267.00
REAR BOOTLID LOCK OUTER OPENER SWITCH <i>Dengd</i>	1	143.10	✓ 143.10
REAR BOOTLID LOCK STRIKER <i>Best</i>	1	15.30	✓ 15.30
REAR BOOTLID MECHANISM LOCK <i>Dengd</i>	1	399.50	✓ 399.50
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	65.90	✗ 131.80
REAR BOOTLID OUTER CHROME HANDLE <i>could</i>	1	193.50	✓ 193.50
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R <i>new</i>	2	27.80	✓ 55.60
REAR BOOTLID REFLECTOR L/R <i>could</i>	2	470.20	640 ✓ 940.40
REAR BOOTLID WEATHER STRIP <i>cut</i>	1	175.80	✓ 175.80
REAR BUMPER <i>Delhd</i>	1	556.40	✓ 556.40
REAR BUMPER REFLECTOR L/R <i>RH could</i>	2	59.80	59.80 ✓ 119.60
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	399.50	✓ 399.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

PAN JUI CHU
BLK 439B SENGKANG WEST AVE #20-317
SINGAPORE 792439

Contact : 96482936, 93884875

ESTIMATE

Repair Code : CLM15324

Date in : 27/09/2021

Vehicle Num. : SMC3630S

Model : TOYOTA COROLLA ALTIS ELEGANCE AUTO

Chassis/Eng# : MR053REH604584761/1ZR0B77779

REAR BUMPER REINFORCEMENT BRACKET L/R	Rlt Bent	2	68.20	68.20 36.40
REAR BUMPER REVERSE SENSOR	Damaged	2	276.80	✓ 553.60
REAR BUMPER REVERSE SENSOR WIRE HARNESS	new	1	289.50	x 289.50
REAR BUMPER SIDE RETAINER L/R	new	2	109.30	✓ 218.60
REAR END PANEL	Distorted	1	670.00	✓ 670.00
REAR END PANEL ANTENNA SENSOR	cracked	1	192.20	✓ 192.20
REAR END PANEL INNER TOP GARNISH	cracked	1	241.90	✓ 241.90
REAR EXHAUST GASKET	new	1	53.40	+ 53.40
REAR EXHAUST HEAT COVER	new	1	31.80	+ 31.80
REAR EXHAUST RUBBER MOUNTING	new	2	49.10	+ 98.20
REAR EXHAUST SILENCER BOX	Repair	1	1124.90	x 1,124.90
REAR FENDER INNER SHIELD L/R	RH Dented	2	55.10	55.10 110.20
REAR FENDER INNER TRIM BOARD L/R	Dented	2	370.90	✓ 741.80
REAR FLOOR PANEL TOP BOARD COVER	torn	1	364.20	✓ 364.20
REAR RH FENDER	Buckled	1	1149.80	✓ 1,149.80
REAR TAILLAMP INNER BLACK GASKET L/R	new	2	27.60	✓ 55.20
REAR TAILLAMP INNER PANEL L/R	Rlt Dented	2	111.10	111.10 222.20
REAR TAILLAMP L/R	cracked	2	497.30	✓ 994.60

760

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

PAN JUI CHU
BLK 439B SENGKANG WEST AVE #20-317
SINGAPORE 792439

Contact : 96482936, 93884875

ESTIMATE

Repair Code : CLM15324

Date in : 27/09/2021

Vehicle Num. : SMC3630S

Model : TOYOTA COROLLA ALTIS ELEGANCE AUTO

Chassis/Eng# : MR053REH604584761/1ZR0B77779

REAR TAILLAMP LOWER BRACKET L/R	Outld	2	60.40	✓	120.80
REAR WINDSCREEN	lt	1	1559.20	1240	1,559.20
Subtotal before discount					13,457.70
Percentage discount 25%					3,364.43
Sub-total 1					10,093.28
REAR BOOTLID CAMERA	Pangd	1	800.00	380	800.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	neu	1	50.00	30	50.00
REAR BOOTLID NUMBER PLATE	Best	1	25.00	✓	25.00
REAR BOOTLID NUMBER PLATE HOLDER	Delld	1	50.00	30	50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	neu	1	50.00	10	50.00
REAR BUMPER CLIPS - SET	neu	1	50.00	30	50.00
REAR BUMPER TOP RUBBER COVER	Delld	1	300.00	200	300.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	neu	1	40.00	10	40.00
REAR FENDER INNER SHIELD CLIPS L/R - SET	neu	2	30.00	10	60.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	neu	2	50.00	60	100.00
REAR FLOOR PANEL INSULATOR MAT	neu	1	300.00	+	300.00
REAR TAILLAMP CLIPS L/R - SET	neu	2	25.00	20	50.00
REAR WINDSCREEN 3D SOLAR FILM	neu	1	280.00	200	280.00

*** This is a computer-generated document which requires no signature. ***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

PAN JUI CHU
BLK 439B SENGKANG WEST AVE #20-317
SINGAPORE 792439

Contact : 96482936, 93884875

ESTIMATE

Repair Code : CLM15324

Date in : 27/09/2021

Vehicle Num. : SMC3630S

Model : TOYOTA COROLLA ALTIS ELEGANCE AUTO

Chassis/Eng# : MR053REH604584761/1ZR0B77779

REAR WINDSCREEN SEAL	1	1085	80.00	40	80.00
REAR WINDSCREEN SEALANT	1		80.00	40	80.00
Subtotal before discount					2,315.00
Percentage discount 0%					0.00
Sub-total 2					2,315.00
Parts-total					12,408.28

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector	✓	80.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓	80.00
To remove, reinstall windscreen (REAR)	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	120.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1200	1,400.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	80	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3020	1300 1,600.00
To apply anti-rust chemical on repaired and replaced panel.	80	120.00
Labour Total		3,650.00
Parts & Labour Total		16,058.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to computer generated document which requires no signature.***
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/3 29/09/21

09 Days

total: 11978.72

2/3 9.51K