

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

pp s. be minor electric.

1/11/21 4/5 @ 3500 confirmed with yonhony

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) \$ + RS \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO.: 35766600C

GST REG. NO.: 35766600C

23-10-21

Date Of Accident : 24-09-2021

OUR REF : GBK 9080C/T/21

GOURMETZ PTE LTD

6A Wan Lee Road

Singapore 627938

JKK Mercedes

Date In/Out: 11/10/21 to 16/10/21

Not Authorised
11/10/21
2/523500/
1 the dr. 11/10/21
5 days.

ESTIMATE BILL ON VEH. NO. : GBK 9080C

MODEL : TOYOTA DYNA

CHASSIS NO : JTFAT35Y50K216126

LIST ITEM

Wiper Panel		5.15.00	971.45	✓
Wiper Panel Clips	8pcs @ 12.90	11	103.20	X
Front Panel	1194.30	Body 00	1,218.10	✓
Dyna "Emblem"		111	121.10	✓
Front Grille Clips	10pcs @ 12.90	11	129.00	X
Front Corner Panel - RH		R	671.75	X
Front Corner Panel Clips	2pcs @ 12.90	11	25.80	X
Wing Mirror Bracket	115	600.00	300	688.95
Wing Mirror Bracket Motor	115	shorted/banged	789.10	✓
Round Mirror	115	cut	145.20	✓
			4,860.65	
			Less Discount 25%:	1,215.16
				3,645.49

SPECIAL NETT ITEM

01 Sticker (Front)	111	25.00	✓
--------------------	-----	-------	---

LABOUR CHARGE

To Remove & Refix Front Windscreen Glass.	100	180.00	
To Check Wiring.	20	80.00	

To Remove & Refit Dashboard Fascia,, Instrucment Member, Wiring To Facilitate Job Repair.

250 480.00

To Remove & Refix Interior Upholstery.

11 120.00 X

To Remove & Refix Air Cond Evaporator, Vacuum & Recharge Gas.

100 280.00

Towing.

11 100.00 X

To Remove & Replace Damaged Parts, Cut & Weld Front Panel, Straighten & Repair & Aligned All Parts.

600 1,150.00

To Respray Affected Areas.

500 900.00

6,960.49

GST 7%: 487.23

TOTAL AMOUNT : 7,447.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-3821-28
257
P-286593
S.N-28
A-