



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202821

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 17/05/2022  
Reference CC6/CTI21010096/Kea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SKP 9674G  
Insured Veh. GBH 5800J  
Claim No. SNM21D205539/C02  
Policy No. DMCVSNW00089242103  
Accident Date 10/09/2021  
Inspection Date 30/09/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21010096/Kea3q2	
			Date: 17/05/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBH 5800J	Veh. Inspected	SKP 9674G	
Policy No.	DMCVSNW00089242103	Coverage (\$)	0.00	
Claim No.	SNM21D205539/C02	Excess (\$)	0.00	
Assign From		Assign Date	30/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALPHARD (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTEGD21H208346499	Colour	METALLIC SILVER	
Odometer	115864 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	7 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/09/2021	Inspection Date	30/09/2021	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 9674G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b><u>REPLACEMENT OF PARTS</u></b>	SERVICEABLE		
	FRONT RH BUMPER RETAINER		109.30	-
	LESS 25% DISCOUNT		-27.33	-
			81.97	-
	<b><u>LABOUR</u></b>			
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.		400.00	200.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		500.00	400.00
			900.00	600.00
<b>GRAND TOTAL</b>			<b>981.97</b>	<b>600.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>600.00</b>

Report Ref No. CC6/CTI21010096/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKP 9674G

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

