

Huey Yon (LKKAUTO)

From: Huey Yon (LKKAUTO)
Sent: Thursday, 1 September 2022 1:57 PM
To: Assessment Dept
Cc: SUR
Subject: RE: Re finalisation of SKJ 5093R

Dear Sir,

Any updates?

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Huey Yon (LKKAUTO)
Sent: Monday, 4 July 2022 4:55 PM
To: TG Lim (LKK Auto) <TeowGuan@lkkauto.com>; Assessment Dept <assessment_ral@bifrostauto.com>
Subject: RE: Re finalisation of SKJ 5093R

Dear Andrew,

Please check and confirm your LOD have amend the COR to Lump Sum \$14,000.00 instead of \$16,300.00.
Kindly acknowledge and reply to us of above matter asap.

Best Regards,

Huey Yon | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TG Lim (LKK Auto) <TeowGuan@lkkauto.com>
Sent: Saturday, 19 March 2022 1:45 PM
To: Assessment Dept <assessment_ral@bifrostauto.com>
Cc: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: Re finalisation of SKJ 5093R

Hi Andrew,

Without Prejudice

Attached is the amended estimate of SKJ 5093R

We will be advising our Principal a cost of repair of LS \$14,000/- with 7 days of repair, subject to their approval.

Please amend your LOD.

Please take note that there was an error of offering the NV as the COR.
My apologies for the error made.

Best Regards,

TG Lim | Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: TeowGuan@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)