

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for YP8619H(Mitsubishi Canter)

2018

1 *REAR TAILGATE	1800.00	\$2,850.30 DD ✓
1 *REAR TAILLAMP RH		\$517.40 NDX
1 *REAR TAILLAMP LH	226.25	\$517.40 BRV ✓
1 *REAR TAILLAMP BRACKET RH		\$196.44 NDX
1 *REAR TAILLAMP BRACKET LH		\$196.44 BT ✓
4 *REAR TAILGATE HINGE	231.70	\$352.17 NEC ✓
1 *REAR TAILGATE LOWER PANEL		\$747.35 NDX
1 *REAR TAILGATE LOWER PANEL NUMBER PLATE BRACKET		\$128.96 } NDX
1 *REAR TAILGATE LOWER PANEL NUMBER PLATE LAMP		\$62.70 }
1 *REAR TAILGATE LOWER PANEL STEP BRACKET		\$479.30 NDX
1 *REAR TAILGATE OUTER LOCK HANDLE LH		\$221.52 JM ✓
1 *REAR TAILGATE OUTER LOCK HANDLE RH		\$221.52 NDX
	2675.91	\$6,491.50
Less 10%	267.59	\$649.15
	2408.32	\$5,842.35

S/Nett

*REAR TAILGATE 60KM/H STICKER	10.00	\$40.00 NEC ✓
*REAR NUMBER PLATE		\$50.00 NDX
*REAR REINFORCEMENT BAR	480.00	\$800.00 BT ✓
	490.00	\$890.00

CHECK REAR WIRING AND LIGHTING SYSTEM		\$60.00 NNX
TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	100.00	\$200.00 ✓
PANEL BEATING ON AFFECTED AREAS	400.00	\$1,000.00 ✓
SPRAY PAINTING ON AFFECTED AREAS	400.00	\$1,000.00 ✓
APPLY ANTI RUST ON AFFECTED AREA		\$200.00 NNX
	900.00	\$2,460.00

Total

\$9,192.35

Survey 1/10/2021
Return 13.10 hrs
No Resurvey necessary
Lump sum repair
Repair days 4

Parts 2408.32
SN 490.00
Labour 900.00
3798.32
759.66
3038.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LS 3050/2

TG Kim
5/10/2021