

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for YP8619H(Mitsubishi Canter)

2018

1 *REAR TAILGATE	1800.00	\$2,850.30	DD ✓
1 *REAR TAILLAMP RH		\$517.40	NDX
1 *REAR TAILLAMP LH	226.25	\$517.40	BRV ✓
1 *REAR TAILLAMP BRACKET RH		\$196.44	NDX
1 *REAR TAILLAMP BRACKET LH		\$196.44	BT ✓
4 *REAR TAILGATE HINGE	231.70	\$352.17	NE ✓
1 *REAR TAILGATE LOWER PANEL		\$747.35	NDX
1 *REAR TAILGATE LOWER PANEL NUMBER PLATE BRACKET		\$128.96	NDX
1 *REAR TAILGATE LOWER PANEL NUMBER PLATE LAMP		\$62.70	NDX
1 *REAR TAILGATE LOWER PANEL STEP BRACKET		\$479.30	NDX
1 *REAR TAILGATE OUTER LOCK HANDLE LH		\$221.52	JM ✓
1 *REAR TAILGATE OUTER LOCK HANDLE RH		\$221.52	NDX
		\$6,491.50	
Less 10%	2675.91	\$649.15	
	267.59	\$5,842.35	
	2408.32		

S/Nett

*REAR TAILGATE 60KM/H STICKER	10.00	\$40.00	NE ✓
*REAR NUMBER PLATE		\$50.00	NDX
*REAR REINFORCEMENT BAR	480.00	\$800.00	BT ✓
	490.00	\$890.00	

CHECK REAR WIRING AND LIGHTING SYSTEM

TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	100.00	\$60.00	NNX
PANEL BEATING ON AFFECTED AREAS	400.00	\$200.00	✓
SPRAY PAINTING ON AFFECTED AREAS	400.00	\$1,000.00	✓
APPLY ANTI RUST ON AFFECTED AREA	400.00	\$1,000.00	✓
		\$200.00	NNX
	900.00	\$2,460.00	

Total

\$9,192.35

Survey 1/10/2021
Return 13.0 hrs
No Resurvey necessary
Lump sum repair
Repair days 4

Parts 2408.32
SN 490.00
Labour 900.00
3798.32
759.66
3038.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LS 3050/2

TG Lim
5/10/2021