



# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A  
#03-11 AMK Autopoint Singapore 568047  
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authorized  
Resurvey B4paint*

*5 days  
\$ 4266.00*

## ESTIMATE

Auto & General Insurance (Singapore) Pte Ltd  
Singapore Shopping Centre  
190 Clemenceau Ave #03-01  
Singapore 239924  
Attn: Accident Claims Department

Date : 29.09.2021  
Vehicle No : SKQ8996D  
Veh Make/Model : Mazda CX-5  
YOM : 2018  
Chassis No : JM6KF2W7AK0241299  
Date of Accident : 29/09/2021

4302.20

No	Qty	Description	Amount \$
<b>List Items:-</b>			
1	1	Front Bonnet	\$ <i>R</i> 1,076.30 ✓
2	1	Front Radiator Top Garnish	\$ <i>my car</i> 299.30 ✓
3	1	Front Bumper <i>1023-10</i>	\$ <i>Bu</i> 1,023.10 ✓
4	2	Front Bumper Side Retainer	\$ <i>R</i> 31.00 X
5	1	Front Bumper Sponge	\$ <i>Sm</i> 47.80 X
6	1	Front Grille Base With Chrome <i>1020</i>	\$ <i>CM</i> 1,071.00 ✓
7	1	Front Logo	\$ <i>RM</i> 95.10 ✓
8	1	Front Logo Holder	\$ <i>CM</i> <del>57.70</del> 57.70 ✓
9	2	Front Lower RH Side Cover / Garnish	\$ <i>Sm</i> 39.20 X
10	1	Towing Cover	\$ <i>Sm</i> 13.60 X
11	1	Front Reinforcement Bar	\$ <i>R</i> 614.10 X
12	2	Front Bumper Sensor	\$ <i>R</i> 361.80 X
13	1	Rear Bumper	\$ <i>R</i> 1,278.90 X
14	2	Rear Bumper Side Retainer	\$ <i>Sm</i> 47.40 X
15	2	Rear Bumper Towing Cover	\$ <i>R</i> 12.00 X
16	1	Rear Reinforcement Bar	\$ <i>R</i> 520.00 X
17	2	Rear Reinforcement Arm	\$ <i>R</i> 50.80 X
18	1	Exhaust Box	\$ <i>R</i> 1,485.80 X
19	Set	Exhaust Mounting	\$ <i>Sm</i> 140.00 X
20	2 Set	Reverse Sensor	\$ <i>R</i> 361.80 X
21			
22			
23			
24			
25			
26			
<b>Total - List Item</b>			\$ 7,550.40
<b>Less 25%</b>			\$ <i>20%</i> 7,550.15
<b>Total</b>			\$ 1,926.75

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

