

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KAMARUYAQZAN BIN YAZID
BLK 527 HOUGANG AVE 6 #13-213
SINGAPORE 530527

Contact : 90258241

ESTIMATE

Repair Code : CLM15321
Date in : 27/09/2021
Vehicle Num. : SMA3767S
Model : HONDA CIVIC 1.6L 5AT
Chassis/Eng# : JHMFD46209S200941/R16A14003498

TP chin.
Xiao Chen.

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Distorted</i>	1	873.90	873.90 683.90
FRONT BUMPER REINFORCEMENT <i>Painted</i>	1	309.50	✓ 309.50
FRONT BUMPER RH FOGLAMP GARNISH <i>all in</i>	1	40.00	40.00 X 40.00
FRONT BUMPER SIDE RETAINER L/R <i>RH Paint</i>	2	18.00	36.00 18.00
FRONT CHASSIS SIDE MEMBER RH <i>Paint</i>	1	450.00	+ 450.00
FRONT HEADLAMP L/R <i>RH ut.</i>	2	1100.00	2200.00 1100.00
FRONT HEADLAMP LOWER BRACKET L/R <i>new RH Bent</i>	2	27.50	55.00 27.50
FRONT RH FENDER <i>Distorted</i>	1	606.80	606.80 537.00
FRONT RH FENDER INNER BRACKET <i>3 legs</i>	1	18.00	+ 18.00
FRONT RH FENDER INNER PANEL	1	121.60	+ 121.60
FRONT RH FENDER INNER SHIELD <i>torn</i>	1	127.60	✓ 127.60
FRONT WASHER TANK <i>3 legs Delid</i>	1	98.00	✓ 98.00
FRONT WASHER TANK MOTOR <i>all in</i>	1	105.00	+ 105.00
Subtotal before discount			5,041.40
Percentage discount 20%			1,008.28
Sub-total 1			4,033.12
FRONT BUMPER CLIPS - SET <i>Na</i>	1	50.00	50.00 30.00
FRONT BUMPER LOWER SPOILER <i>ut</i>	1	800.00	800.00 600.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

KAMARUYAQZAN BIN YAZID

BLK 527 HOUGANG AVE 6 #13-213

SINGAPORE 530527

Contact : 90258241

ESTIMATE

Repair Code : CLM15321

Date in : 27/09/2021

Vehicle Num. : SMA3767S

Model : HONDA CIVIC 1.6L 5AT

Chassis/Eng# : JHMFD46209S200941/R16A14003498

FRONT GRILLE	<i>HE M</i>	1	500.00	<i>+</i>	500.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	<i>HE M</i>	1	50.00	<i>30</i>	50.00
Subtotal before discount					1,400.00
Percentage discount 0%					0.00
Sub-total 2					1,400.00
Parts-total					5,433.12

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,880.00
Parts & Labour Total	7,313.12

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adam Lj
30/09/21
L/S. 04 Days
total: 405048
L/S: 32K ✓