

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERS SINGAPORE 048623			Ref: CS3/SMO21010120/Kv3 Date: 30/09/2021 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMR 6423A	Veh. Inspected	SKZ 28D	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2102902/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	30/09/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/09/2021	Inspection Date	04/10/2021	
Survey held at	AH KOON MOTOR **Cancelled** BLK 1001 BUKIT MERAH LANE 3 #01-69 SINGAPORE 159718			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				