



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21010123/Kuf3e2	
			Date: 16/11/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1728Y	Veh. Inspected	SMA 2026D
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/09/21/2050	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	30/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WDC2539462F408454	Colour	METALLIC DARK BLUE
	Odometer	50548 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	PIRELLI	6 mm
	L/H Front Tyre	235/60 R18	PIRELLI	6 mm
	R/H Rear Tyre	235/60 R18	SCORPION	7 mm
	L/H Rear Tyre	235/60 R18	SCORPION	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/09/2021	Inspection Date	12/10/2021
	Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	