



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 30/09/21
LKK - STEVE

VEHICLE NO : SMW 5531B

MODEL : CIT/C5 Arcross 180

WIP : 16970

Material	:	\$	<u>4,104.00</u>
Labour	:	\$	<u>1,635.00</u>
Sub-Total	:	\$	<u>5,739.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>5,139.00</u>
GST 7%	:	\$	<u>359.73</u>
Grand Total	:	\$	<u>5,498.73</u>

Finalise By/Date : LARRY ON 05/11/21



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS + 2 days (wk. end)

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name FCV02045/IVAN LEE HSI MENG Reg No/Reg Date SMW5531B / 26/11/2020 Date In/Mileage 30/09/2021/ 13564 Chassis/Package VR7A45GFRL059895 /# Engine No 10FKBL2679705 Make/Model CIT/C5 AIRCROSS PURETECH 180 S&S EAT 8 S Colour/Trim POW POLAR WHITE/ RE/ OXF CUIR CLAUDIA/TI



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	05/11/2021/ 09:12	BLC	884 / Lauro Songcuan	16970	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER				500.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER				380.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				225.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT FENDER RH → <i>Supp.</i>				380.00 ✗
X EXC EXCESS FOR OWN DAMAGE CLAIM				-600.00
X FRONT BUMPER ✓	1.00	1502.00	20.00	1201.60 ✓
X BRACKET SET ?	1.00	109.00	20.00	87.20 ?
X FINISHER BUMPER ?	1.00	93.00	20.00	74.40 ?
X FINISHER BUMPER ✓	1.00	116.00	20.00	92.80 ✓
X REAR DUCT ?	1.00	167.00	20.00	133.60 ?
X REAR DUCT ?	1.00	88.00	20.00	70.40 ?
X BUMPER BRACKET ?	1.00	342.00	20.00	273.60 ?
X FIXING STUD ✓	1.00	36.00	20.00	28.80 ✓
X FRONT LIGHT RH ?	1.00	770.00	20.00	616.00 ?
X HDLIGHT SUPPORT RH COMPLEMENTA ?	1.00	72.00	20.00	57.60 ?
X LIGHT MOULDING RH AV ?	1.00	90.00	20.00	72.00 ?
X HEADLIGHT ASSY RH ?	1.00	691.00	20.00	552.80 ?
X DISTRIB CHAMBER ?	1.00	840.00	20.00	672.00 ?
X DIST CHB BRACKT ?	1.00	43.00	20.00	34.40 ?
X DIST CHB BRACKT ?	1.00	43.00	20.00	34.40 ?
X FOG HEADLIGHT ?	1.00	128.00	20.00	102.40 ?
Z TEXT				

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name FCV02045/IVAN LEE HSI MENG Reg No/Reg Date SMW5531B / 26/11/2020 Date In/Mileage 30/09/2021/ 13564 Chassis/Package VR7A45GFRL059895 /# Engine No 10FKBL2679705 Make/Model CIT/C5 AIRCROSS PURETECH 180 S&S EAT 8 S Colour/Trim POW POLAR WHITE/ RE/ OXF CUIR CLAUDIA/TI

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	05/11/2021/ 09:12	BLC	884 / Lauro Songcuan	16970	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
OD CLAIM - AIG SURVEY: STEVE (LKK) 30/09/2021 DOA: 29/08/2021 03 DAYS				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	4,104.00			
Labour	1,615.00			
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-580.00			
Total(w/o GST)	5,139.00			
		7% GST on	5139.00	
			Nett	5,139.00
				359.73
			Total Payable	5,498.73
			Paid	0.00
			Total Due	5,498.73

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMW 5531 B

<u>Labour</u>		<u>Cost \$</u>
1	Spray Paint for Front Fender RH	380.00 ✓
	7% GST	26.60
	Total	406.60

Thank You.

Yours faithfully
CYCLE & CARRIAGE FRANCE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: SMA5531BWIP: 16970

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	① BUMPER BRACKET (Front panel (3/16))	? / SUPP	7	- RR	98143521 XT
2	① FR BUMPER AIR VENTILATOR DUCT	? / SUPP	(Interlock Outfit)	- RR	98 333 983 80
3	① FR BUMPER AIR VENTILATOR DUCT	? / SUPP	(Interlock, Inlet)	- RR	98 106 171 80
4	① ASST FINISHER BUMPER	? / SUPP	(Bumper Inlet)	- RR	16 384 952 80
5	① BUMPER BRACKET SET	? / SUPP	(b 11")	- RR	16 384 951 80
6	③ FRONT LIGHT (RH) (Small)	? / SUPP	7	- RR	98 348 044 80
7	② HEADLIGHT SUPPORT (RH) (Black)	? / SUPP	7	- RR	98 202 965 XY
8	② LIGHT MOUNTING (RH) (Chime)	? / SUPP		- RR	98 202 952 DX
9	① HEADLIGHT (RH) (Big)	? / SUPP		- RR	98 221 874 80
10	① INTERCOOLER ASSEMBLY	? / SUPP		- RT	96 756 279 80
11	② INTERCOOLER ASSEMBLY BRACKET	? / SUPP		- RT	98 034 791 80
12	④ INTERCOOLER ASSEMBLY BRACKET	? / SUPP		- RR	98 034 789 80
13	① FOG HEADLIGHT (Bumper lower fining)	? / SUPP		- RR	6209 Q3
14		? / SUPP			
15	Spray fit Fender (RH) \$380	? / SUPP			Steve 13/10/91
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: AIRCROSSSURVEYOR: STEVE

Page No. SHW55319
after to use DIAGBOX to
check and see all the fault by Qc Test



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

1  Built-in systems interface BSI2010_EV (1 Faults)

B133D 13

Front window relay control output fault

Properties

Cause

Local

Status

Present

Features

Open circuit




Engine management ECU

CMM_MG1CS042



Urea ECU

Communication error



Automatic or piloted manual gearbox


★ ECU not recognised

Down-grade mode: this information is not guaranteed



Sequential gear lever

ESM



Sequential gear lever

Communication error



Power steering

DAE_BVH2



Anti-lock Braking System (ABS)
 or Electronic Stability Program
 (ESP)

ESP90




Motorised Boot Unit

VERINS_MOTORISES



Hands full access ECU, right-hand side or rear

BAAST



Air conditioning

BCC




Additional heating

Communication error




Electric steering lock

AVE




Diesel additive pump

Not present



Electric machine management ECU

Not present



Electrical brake servo master cylinder

Not present



Traction battery ECU

Not present



On-board charger / direct voltage transformer assembly

Not present



Electric/hybrid drive train supervisor ECU

Not present




Ancillaries battery 1 switch

Not present



Ancillaries battery 2 switch

Not present



Voltage maintaining device

Not present



Dynamic headlamp height adjuster

Not present



**Passenger's seat pneumatic
functions ECU**

Not present

Help