



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200909327M
GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
IVAN LEE HSI MENG 45 TEBAN GARDENS ROAD #04-414 SINGAPORE 600045 Contact No	Cust No/Name FCV02045/IVAN LEE HSI MENG Reg No/Reg Date SMW5531B / 26/11/2020 Date In/Mileage / 0 Chassis No VR7A45GFRLL059895 Engine No 10FKBL2679705 Make/Model CIT/C5 AIRCROSS PURETECH 180 S&S EAT 8 S Colour/Trim POW POLAR WHITE/ RE/ OXF CUIR CLAUDIA/TI

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
FCV02045	CRDVCH	28/09/2021/ 17:17	BLC	442 / CocoLu	16970

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER,				500.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00 ✓
E PNT98000 SPRAY PAINT FOR FRT BUMPER				380.00 ✓
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				225.00 ✓
M SUNDRY Sundry				20.00 ✓
A 54900099 RENEW INTERCOOLER				250.00 x
M FRONT BUMPER	1.00	1502.00	0.00	1502.00 ✓
M FR BMPR GRILLE	1.00	993.00	0.00	993.00 ✓
M BRACKET SET	1.00	109.00	0.00	109.00 ✓
M FINISHER BUMPER	1.00	93.00	0.00	93.00 ✓
M FINISHER BUMPER	1.00	116.00	0.00	116.00 ✓
M BUMPER ABSORBER	1.00	156.00	0.00	156.00 ✓
M BRACKET SET	1.00	109.00	0.00	109.00 ✓
M REAR DUCT	1.00	167.00	0.00	167.00 ✓
M REAR DUCT	1.00	88.00	0.00	88.00 ✓
M BUMPER BRACKET	1.00	342.00	0.00	342.00 ✓
M BUMPER ABSORBER	1.00	370.00	0.00	370.00 ✓
M BUMPER ABSORBER	1.00	499.00	0.00	499.00 ✓
M FIXING STUD	1.00	36.00	0.00	36.00 ✓
M FRONT LIGHT RH	1.00	770.00	0.00	770.00 ✓
M HDLIGHT SUPPORT RH COMPLEMENTA	1.00	72.00	0.00	72.00 ✓
M LIGHT MOULDING RH AV	1.00	90.00	0.00	90.00 ✓
M HEADLIGHT ASSY RH	1.00	691.00	0.00	691.00 ✓
M DISTRIB CHAMBER	1.00	840.00	0.00	840.00 ✓
M DIST CHB BRACKT	1.00	43.00	0.00	43.00 ✓

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200509327M
GST Reg No. MR-8509111-X

Invoice Name & Address			Owner Name & Vehicle Info		
IVAN LEE HSI MENG			Cust No/Name	FCV02045/IVAN LEE HSI MENG	
45 TEBAN GARDENS ROAD			Reg No/Reg Date	SMW5531B / 26/11/2020	
#04-414			Date In/Mileage	/ 0	
SINGAPORE 600045			Chassis No	VR7A45GFRLL059895	
Contact No			Engine No	10FKBL2679705	
			Make/Model	CIT/C5 AIRCROSS PURETECH 180 S&S EAT 8 S	
			Colour/Trim	POW POLAR WHITE/ RE/ OXF CUIR CLAUDIA/TI	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
FCV02045	CRDVCH	28/09/2021/ 17:17	BLC	442 / CocoLu	16970

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	DIST CHB BRACKT	1.00	43.00	0.00	43.00
M	DIST CHB BRACKT	1.00	43.00	0.00	43.00
M	FOG HEADLIGHT	1.00	128.00	0.00	128.00

Estimate

Ster CLKK)
30/9/21, 4.30pmOD- AL AL
EXCISE - ?
P/P
My Bel sy
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

Parts	7,300.00
Labour	1,485.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	20.00
Total(w/o GST)	8,805.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.