



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
IVAN LEE HSI MENG	Cust No/Name FCV02045/IVAN LEE HSI MENG
45 TEBAN GARDENS ROAD	Reg No/Reg Date SMW5531B / 26/11/2020
#04-414	Date In/Mileage / 0
SINGAPORE 600045	Chassis No VR7A45GFRL059895
Contact No	Engine No 10FKBL2679705
	Make/Model CIT/C5 AIRCROSS PURETECH 180 S&S EAT 8 S
	Colour/Trim POW POLAR WHITE/ RE/ OXF CUIR CLAUDIA/TI

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
FCV02045	CRDVCH	28/09/2021/ 17:17	BLC	442 / CocoLu	16970

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER,				500.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				380.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				225.00
M SUNDRY Sundry				20.00
A 54900099 RENEW INTERCOOLER				250.00
M FRONT BUMPER	1.00	1502.00	0.00	1502.00
M FR BMPR GRILLE	1.00	993.00	0.00	993.00
M BRACKET SET	1.00	109.00	0.00	109.00
M FINISHER BUMPER	1.00	93.00	0.00	93.00
M FINISHER BUMPER	1.00	116.00	0.00	116.00
M BUMPER ABSORBER	1.00	156.00	0.00	156.00
M BRACKET SET	1.00	109.00	0.00	109.00
M REAR DUCT	1.00	167.00	0.00	167.00
M REAR DUCT	1.00	88.00	0.00	88.00
M BUMPER BRACKET	1.00	342.00	0.00	342.00
M BUMPER ABSORBER	1.00	370.00	0.00	370.00
M BUMPER ABSORBER	1.00	499.00	0.00	499.00
M FIXING STUD	1.00	36.00	0.00	36.00
M FRONT LIGHT RH	1.00	770.00	0.00	770.00
M HDLIGHT SUPPORT RH COMPLEMENTA	1.00	72.00	0.00	72.00
M LIGHT MOULDING RH AV	1.00	90.00	0.00	90.00
M HEADLIGHT ASSY RH	1.00	691.00	0.00	691.00
M DISTRIB CHAMBER	1.00	840.00	0.00	840.00
M DIST CHB BRACKT	1.00	43.00	0.00	43.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
IVAN LEE HSI MENG	Cust No/Name FCV02045/IVAN LEE HSI MENG
45 TEBAN GARDENS ROAD	Reg No/Reg Date SMW5531B / 26/11/2020
#04-414	Date In/Mileage / 0
SINGAPORE 600045	Chassis No VR7A45GFRL059895
Contact No	Engine No 10FKBL2679705
	Make/Model CIT/C5 AIRCROSS PURETECH 180 S&S EAT 8 S
	Colour/Trim POW POLAR WHITE/ RE/ OXF CUIR CLAUDIA/TI

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
FCV02045	CRDVCH	28/09/2021/ 17:17	BLC	442 / CocoLu	16970

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M DIST CHB BRACKT	1.00	43.00	0.00	43.00
M DIST CHB BRACKT	1.00	43.00	0.00	43.00
M FOG HEADLIGHT	1.00	128.00	0.00	128.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Parts	7,300.00
Labour	1,485.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	20.00
Total (w/o GST)	8,805.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.