

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

Name : CHOW CHUAN JUN

Vehicle No : SJF 1553 P

To ALG.

Asher.

Make/Model : SUZUKI SWIFT

Accident date : 23.09.2021

| No                | DESCRIPTION                                          | Qty | Amount (\$S)                |
|-------------------|------------------------------------------------------|-----|-----------------------------|
| <b>List Items</b> |                                                      |     |                             |
| 1                 | Front bonnet <i>cracked</i>                          | 1   | \$ 1,500.00 <i>1000(SN)</i> |
| 2                 | Front bonnet hinges @ \$37.70 <i>new</i>             | 2   | \$ 75.40 <i>x</i>           |
| 3                 | Front bonnet lock                                    | 1   | \$ 66.30 <i>x</i>           |
| 4                 | Front bonnet lock bracket <i>2 NP</i>                | 1   | \$ 50.70 <i>x</i>           |
| 5                 | Front support panel <i>new</i>                       | 1   | \$ 180.00 <i>x</i>          |
| 6                 | Front headlamp @ \$665.00 <i>LH ut</i>               | 2   | \$ 1,330.00 <i>665</i>      |
| 7                 | Front grille <i>cracked</i>                          | 1   | \$ 180.00                   |
| 8                 | Front bumper <i>Deformed</i>                         | 1   | \$ 1,500.00 <i>750(SN)</i>  |
| 9                 | Front bumper side holder @ \$40.30 <i>new</i>        | 2   | \$ 80.60 <i>x</i>           |
| 10                | Front bumper centre lower grille <i>new</i>          | 1   | \$ 180.00 <i>x</i>          |
| 11                | Front bumper lower side grille @ \$100.00 <i>new</i> | 2   | \$ 200.00 <i>x</i>          |
| 12                | Front bumper reinforcement <i>new</i>                | 1   | \$ 247.00 <i>x</i>          |
| 13                | Front bumper reinforcement cover <i>new</i>          | 1   | \$ 156.00 <i>x</i>          |
| 14                | Front bumper sponge <i>new</i>                       | 1   | \$ 105.00 <i>x</i>          |
| 15                | Front number plate garnish <i>del</i>                | 1   | \$ 55.00 <i>x</i>           |
| 16                | Aircond condenser <i>new</i>                         | 1   | \$ 816.40 <i>x</i>          |
| 17                | Rear bumper <i>del</i>                               | 1   | \$ 713.70 <i>385</i>        |
| 18                | Rear bumper lower lip <i>new</i>                     | 1   | \$ 850.00 <i>500(SN)</i>    |
| 19                | Rear bumper lower RH reverse lamp <i>cracked</i>     | 1   | \$ 78.00 <i>x</i>           |
|                   |                                                      |     | \$ 8,364.10                 |
| Less 15% Disc     |                                                      |     | \$ 1,254.62                 |
| Total             |                                                      |     | \$ 7,109.49                 |

### Special Nett Items

|       |                                       |   |                    |
|-------|---------------------------------------|---|--------------------|
| 1     | Front number plate <i>cracked</i>     | 1 | \$ 50.00 <i>30</i> |
| 2     | Front number plate holder <i>del</i>  | 1 | \$ 50.00 <i>30</i> |
| 3     | Front grille clips (1 set) <i>new</i> | 1 | \$ 60.00 <i>20</i> |
| Total |                                       |   | \$ 160.00          |

### Labour Cost

|       |                                                     |   |                        |
|-------|-----------------------------------------------------|---|------------------------|
| 1     | Remove & refix reverse sensor                       | 1 | \$ 150.00 <i>50</i>    |
| 2     | Remove & refix aircond fill in gas                  | 1 | \$ 150.00 <i>x</i>     |
| 3     | Remove, replace & repair consistent to the accident | 1 | \$ 1,500.00 <i>700</i> |
| 4     | Respray painting                                    | 1 | \$ 1,300.00 <i>400</i> |
| Total |                                                     |   | \$ 3,100.00            |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total

\$ 10,369.49

AK

Total: \$5009.66

A/s: AK

OG Dmyr