



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS/CTI21010130/Guc	
3 ANSON ROAD #16-00		Date: 30/09/2021	
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKW 5781U	Veh. Inspected	SGR 7685A
Policy No.	DMPCSNW00150232000	Coverage (\$)	0.00
Claim No.	SNM21D205351/C02/SKW5781 U/CHEESC	Excess (\$)	0.00
Assign From	CHEE SO CHOW	Assign Date	30/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	20/09/2021	Inspection Date	30/09/2021
Survey held at	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING		
Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			