

AUTO BULLOX PTE.LTD

53 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park S(408934)

Business Reg No: 201919765N
Tel: 6841 5383 / Fax: 6841 6043
E-Mail: autobullox@gmail.com

To: Motor Claims Department

TP Somp
Denise.

Date: 27/09/2021

Vehicle No: SGR6732D
Model: Mitsubishi Lancer

Estimated Repair Cost For SGR6732D (Mitsubishi Lancer)

QTY	Parts	Amount
1	Front bumper <i>Del'd</i>	\$ 695.80 ✓
1	Front bumper number plate garnish <i>could</i>	\$ 68.50 ✓
1	Front bumper beam <i>Best</i>	\$ 186.00 ✓
2	Front bumper side bracket @ SGD 92.40 <i>men</i>	\$ 184.80 88. ✓
1	Front bumper lower lip <i>men</i>	\$ 296.70 +
1set	Front bumper clips <i>men</i>	\$ 48.00 ✓
1set	Front radiator grille assy <i>at</i>	\$ 276.40 ✓
1	Front radiator grille logo <i>pec</i>	\$ 75.80 ✓
2	Headlamp assy @ SGD 697.20 (Black Based) <i>could</i>	\$ 1,394.40 ✓
2	Headlamp lower bracket @ SGD 49.60 <i>men</i>	\$ 99.20 +
1	Front bonnet <i>Buckled</i>	\$ 786.40 ✓
1	Front bonnet lock <i>men</i>	\$ 118.40 ✓
1	Front support panel <i>Buckled</i>	\$ 386.70 ✓
1	Front air-duct <i>men</i>	\$ 128.60 +
2	Front fender @ SGD 586.50 <i>RT Buckled</i>	\$ 1,173.00 586.50 ✓
2	Front fender inner shield @ SGD 118.60 <i>men</i>	\$ 237.20 +
1set	Front fender inner shield clips	\$ 42.00 +
1	Front door RH <i>Repair</i>	Repair +
1	Bootlid panel <i>Repair</i>	\$ 684.70 +
1	Bootlid weatherstrip <i>men</i>	\$ 169.40 +
1	Bootlid inner lock <i>men</i>	\$ 167.20 +
1	Bootlid number plate garnish <i>men</i>	\$ 195.70 ✓
2	Taillamp @ SGD 655.20 (White Based) <i>men</i>	\$ 1,310.40 +
1	Rear bumper <i>Del'd</i>	\$ 725.50 ✓
1	Rear bumper centre beam <i>Best</i>	\$ 216.40 ✓
2	Rear bumper side retainer @ SGD 64.20 <i>men</i>	\$ 128.40 ✓
1	End panel top garnish <i>men</i>	\$ 156.40 +
1set	End panel top garnish clips <i>men</i>	\$ 38.00 +
1	End panel <i>Repair</i>	\$ 468.50 +
Parts Sum: \$		10,458.50
Parts Less 10% : \$		1,045.85
Parts Total: \$		9,412.65

5781.20

5203.80

Special Nett Items

1set	Rear Number Plate W/Garnish <i>men</i>	\$ 55.00 +
1set	Reverse Sensor <i>Del'd</i>	\$ 280.00 20 ✓
1set	Front Number Plate W/Garnish <i>Del'd</i>	\$ 55.00 ✓
1	Radiator coolant <i>men</i>	\$ 86.00 50 ✓

Special Nett Items Total: \$ 476.00

305

Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Front & Rear Damaged Areas (\$300.00 per day)	\$ 1,800.00 1300
To Putty, Prep & Re-spray on affected Front & Rear Damaged Areas (\$300.00 per panel) (Front bumper, grille, bonnet, support panel, fender, door / Rear bumper, bootlid, end panel, rear fenders, spare tyre panel)	\$ 1,800.00 1200
To Remove & Transfer Rear Bootlid Components, to Facilitate Repairs	\$ 150.00 X
To Remove & Refit Rear Interior Floor Components to Facilitate Repairs	\$ 150.00 50
To Remove & Install Radiator, to Conduct Pressure Test for Leakage	\$ 150.00 60
To Remove & Install AC Condenser to Facilitate Repairs & Charge Up Gas	\$ 150.00 60
To Measure, Drill Holes on Replaced Rear Bumper, To Re-position & Install Reverse Sensor	\$ 150.00 50
To Conduct Water Seepage Test	\$ 120.00 X.
To Disconnect Rear Wire Harness Electrical Components to Facilitate Repairs	\$ 120.00 60
To Apply Undercoating on the Affected Damaged Areas	\$ 280.00 60

Labour Charges Total: \$ 4,870.00

Parts Total: \$ 9,412.65
 Special Nett Items Total: \$ 476.00
 Labour Charges Total: \$ 4,870.00
 Total Cost Of Repair: \$ 14,758.65
 (Non-Inclusive of GST)

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L

h/s 01/10/21

10 p/s

total: 8348.80

h/s : 2.5K (Nett Value)