

Attn: MR Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

Estimate No: ES2190958/AMK
Date: 06 Oct 2021
Policy No: DMPCSNW00044102100
Veh Reg No: SLC6683G
Make/Model: TOYOTA HARRIER 2.0 PREMIUM

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 27/09/2021
TP Veh Reg No: YQ1688Z

Estimate Repair Cost to Vehicle No :SLC6683G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	602.10	1 PC	602.10	✓
2 FRONT BUMPER REINFORCEMENT	521.70	1 PC	521.70	✗
3 FRONT BUMPER SPONGE	112.20	1 PC	112.20	✓
4 FRONT BUMPER CENTRE LOWER GRILLE	297.30	1 PC	297.30	✓
5 FRONT BUMPER LOWER SPOILER	340.20	1 PC	340.20	✓
6 FRONT BUMPER TOP BEAM	301.10	1 PC	301.10	✓
7 FRONT BUMPER LH SIDE RETAINER	115.20	1 PC	115.20	✗
8 FRONT BUMPER CLIP	4.50	10 PC	45.00	✓
9 BONNET	1,983.90	1 PC	1,983.90	✓
10 BONNET CHROME MOULDING	279.30	1 PC	279.30	✓
11 FRONT GRILLE ASSY	590.60	1 PC	590.60	✓
12 HEADLAMP LH T81070-48890	3,511.90	1 PC	3,511.90	✓
13 HEADLAMP LH TOP PANEL	176.20	1 PC	176.20	✗
14 HEADLAMP LH LOWER PANEL	127.40	1 PC	127.40	✓
15 HEADLAMP LH SPONGE	56.70	1 PC	56.70	✓
16 RADIATOR LH SIDE GARNISH	231.60	1 SET	231.60	✓
			8439.30	6359.48
			Less 25%	-6,969.30
			215.82	
Labour				
17 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, BONNET & ATTACHMENTS, LH HEADLAMP, KNOCKING & REPAIR FRT SUPPORT PANEL & REALIGN LH FENDER THE SAME	500	1 LA	500.00	✓
18 PUTTY & RESPRAY FRT BUMPER, BONNET, FRT LH FENDER, FRT PANEL & ALL AFFECTED AREAS	700	1 LA	700.00	✓
19 RUSTPROOFING	30	1 LA	30.00	✓
			1,230.00	-1,230.00

Parts: 6359.48

L: 1030

7389.48

45 #5900

PLS CHECK & CONFIRM

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 27/09/2021
TP Veh Reg No: YQ1688Z

Estimate No: ES2190958/AMK
Date: 06 Oct 2021
Policy No: DMPCSNW00044102100
Veh Reg No: SLC6683G
Make/Model: TOYOTA HARRIER 2.0
PREMIUM
Chassis No: ZSU600075490
Engine No: 3ZRB760385
Reg. Date: 23/05/2016

Estimate Repair Cost to Vehicle No :SLC6683G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 8,199.30
			Add GST @ 7%	573.95
			Total Amount Payable	<u>S\$ 8,773.25</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE