

ASS. REC. BY:

REF:

MSG/ 21010143/K+

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLE 66836 Yr Regn: 05, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Harrier

C.C.

1988

Colour

M. D. Brown

A/C: Insured / Std / NI / NA

Sp. Reading

75848

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ESU 60 - 0075490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / A/Rim or

Tyre Size:

F:

225/60R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/9/21

D.O.I.

6/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

FINALISE LUMP SUM \$5900, 4DAYS

RED:2299.30;28%

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Not Notified

Estimate No: ES2190958/AMK

Date: 06 Oct 2021

Policy No: DMPCSNW00044102100

Veh Reg No: SLC6683G

Make/Model: TOYOTA HARRIER 2.0 PREMIUM

WS Ref: TP/MSIG/AMK

1/1 Rng &

Chassis No: ZSU600075490

Claim Type: Third Party

Previous After Rain

Engine No: 3ZRB760385

Accident Date: 27/09/2021

Reg. Date: 23/05/2016

TP Veh Reg No: YQ1688Z

4 days

Estimate Repair Cost to Vehicle No :SLC6683G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	602.10	1 PC	602.10	✓
2 FRONT BUMPER REINFORCEMENT	521.70	1 PC	521.70	?
3 FRONT BUMPER SPONGE	112.20	1 PC	112.20	?
4 FRONT BUMPER CENTRE LOWER GRILLE	297.30	1 PC	297.30	2
5 FRONT BUMPER LOWER SPOILER	340.20	1 PC	340.20	✓
6 FRONT BUMPER TOP BEAM	301.10	1 PC	301.10	?
7 FRONT BUMPER LH SIDE RETAINER	115.20	1 PC	115.20	x
8 FRONT BUMPER CLIP	4.50	10 PC	45.00	✓
9 BONNET	1,983.90	1 PC	1,983.90	✓
10 BONNET CHROME MOULDING	279.30	1 PC	279.30	✓
11 FRONT GRILLE ASSY	590.60	1 PC	590.60	✓
12 HEADLAMP LH	3,511.90	1 PC	3,511.90	✓
13 HEADLAMP LH TOP PANEL	176.20	1 PC	176.20	?
14 HEADLAMP LH LOWER PANEL	127.40	1 PC	127.40	?
15 HEADLAMP LH SPONGE	56.70	1 PC	56.70	?
16 RADIATOR LH SIDE GARNISH	231.60	1 SET	231.60	?
			9,292.40	
		Less 25%	2,323.10	6,969.30
Labour				
17 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,LH HEADLAMP;KNOCKING & REPAIR FRT SUPPORT PANEL & REALIGN LH FENDER THE SAME	500	1 LA	500.00	600
18 PUTTY & RESPRAY FRT BUMPER,BONNET,FRT LH FENDER,FRT PANEL & ALL AFFECTED AREAS	700	1 LA	700.00	600
19 RUSTPROOFING	30	1 LA	30.00	✓
			1,230.00	1,230.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/09/2021 18:58 (SGT)
Date of Accident 27/09/2021 15:50 (SGT)
Exact Location of Accident Singapore
Additional Location Information REALTY PARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC6683G

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner WONG FUONG NGIP
NRIC No SXXXX250B
Email Address fuongngip_6@yahoo.com
Mobile Phone No (Phone) +65-91839288
Alternative Phone No +65-91839288

VEHICLE PARTICULARS


Manufacturer Toyota
Model Harrier
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1986

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00044102100
Cover Note Number 26/02/2021 - 25/02/2022

DRIVER

Name of Driver WONG FUONG NGIP
NRIC No SXXXX250B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SLC 66836 (China)

Date & Time: 27/09/2021 @ 1550 (raining/wet)

I was driving behind of YQ1688Z, to exit out of the compound. However, YQ1688Z sudden stop in front and switch on the hazard light and next thing i know was he was reversing the lorry to my car. I quickly sound my horn to alert him and before i could engage my reverse gear to reverse my car away from the lorry, YQ1688Z had reversed and hit onto the front LH portion of my stationary car.

Upon alighting, driver of YQ1688Z was apologetic and he has rung his boss and thereafter pass the phone to me to talk to his boss. His boss has suggested to go to his workshop & he will settled my car repair cost. As it was my first time involved in an accident thus i did not accept his offer and told him to leave it to insurance. That's all.

PLS: Driver of YQ1688Z intention of reversing the lorry was to reverse into back lane of compound

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 28/9/21

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: (AMK)
NRIC/TPN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()