

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/09/2021
User ID : JeongCH

Section A - Accident Details

Registration Number	SMB1397J
Case Reference Number	BUS/09/21/5024
Registration Date	10/16/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Jius Jelius
Type of Accident	Head to Rear
Accident Date and Time	9/21/2021 4:33 PM
Accident Reported Date and Time	9/22/2021 2:49 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1397J-RIGHT REAR BUMPER CRACKED SKV1505H (TP) INSURED WITH AIG
Prepared Date and Time	9/28/2021 1:53 PM
Chassis Number	WMAA22ZZ0D7001919
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$3,894.05	\$0.00
Total Other Cost	\$960.00	\$0.00
TOTAL COST	\$7,760.05	\$0.00
Jump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 day
Prepared / Adjusted By	Bus Zonal Head - Galil Batu Team	
ARC / Surveyor Sign Off Date		
Signature	x	x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 738685
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/09/2021
User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	1325
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$960.00	960
Total Other Costs	\$960.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	cm ✓
010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	cm ✓
010064	Body	F01001-CW274	BUMPER:REAR,CENTRE,FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	repair
010463	Body	S01001-CW006	FRAME,REAR BUMPER:FOR MAN A22 BUS	1.00	\$1,423.20	10.00	\$1,280.88	Replace	repair
Total					\$5,408.40		\$4,867.56		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
3 day)

HS
29/09/21 @1530

Recy after repair