



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202289

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/04/2022
Reference CC3/CTI21010151/Nea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 7686H
Insured Veh. SLK 8261K
Claim No. SNM21D205397/C02
Policy No. DMPCSNW00013242100
Accident Date 22/09/2021
Inspection Date 23/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21010151/Nea3q2	
			Date: 20/04/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 8261K	Veh. Inspected	SH 7686H	
Policy No.	DMPCSNW00013242100	Coverage (\$)	0.00	
Claim No.	SNM21D205397/C02	Excess (\$)	0.00	
Assign From		Assign Date	23/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203560681	Colour	BLUE	
Odometer	610106 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	POOR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2021	Inspection Date	23/09/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7686H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BRACKET FRT BUMPER EXTENS	DEFORMED	99.00	99.00
1	COVER FRONT BUMPER	CRACKED	499.90	499.90
1	COVER FRONT BUMPER HOLE L	SERVICEABLE	28.40	-
1	COVER FRONT BUMPER HOLE R	SERVICEABLE	28.40	-
1	REINFORCEMENT SUB-ASSY FR	BENT	696.40	696.40
1	HOOD SUB-ASSY	DENTED	950.50	950.50
1	UNIT ASSY HEADLAMP RH	CRACKED	2,637.60	2,637.60
1	UNIT ASSY HEADLAMP LH	CRACKED	2,637.60	2,637.60
1	GRILLE SUB-ASSY RADIATOR	DEFORMED	438.00	438.00
1	FENDER SUB-ASSY FRONT RH	DENTED	933.10	933.10
1	LINER FRONT FENDER LH	SERVICEABLE	198.50	-
1	LINER FRONT FENDER RH	SERVICEABLE	198.50	-
1	EMBLEM SIDE PANEL (HYBRID)	NECESSARY	86.50	86.50
1	LAMP ASSY FOG LH	SERVICEABLE	920.00	-
1	LAMP ASSY FOG RH	SERVICEABLE	920.00	-
1	ABSORBER FRONT BUMPER ENE	BROKEN	115.70	115.70
1	SUPPORT SUB-ASSY RADIATOR	SERVICEABLE	234.70	-
1	EMBLEM ASSY RADIATOR GRIL	SERVICEABLE	88.00	-
1	GRILLE RADIATOR LOWER NO	DEFORMED	163.40	163.40
1	HINGE ASSY HOOD LH	BENT	87.70	87.70
1	HINGE ASSY HOOD RH	BENT	87.70	87.70
1	SUPPORT SUB-ASSY RADIATOR	DEFORMED	234.70	234.70
1	SUPPORT SUB-ASSY RADIATOR	DEFORMED	361.10	361.10
1	SUP SUB-ASSY RADIATOR LOW	DEFORMED	393.20	393.20
1	LOCK ASSY HOOD	DEFORMED	132.60	132.60
1	BRACE HOOD LOCK SUPPORT	DEFORMED	46.20	46.20
1	RADIATOR ASSY	DEFORMED	1,841.10	1,841.10
1	CONDENSER ASSY	DEFORMED	1,336.60	1,336.60
1	RADIATOR FAN COVER	CRACKED	451.30	451.30
1	INLET AIR CLEANER NO.3	DEFORMED	34.80	34.80
1	INLET AIR CLEANER NO.2	DEFORMED	93.00	93.00

Report Ref No. CC3/CTI21010151/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	INLET AIR CLEANER NO.1	DEFORMED	129.40	129.40
1	CAP SUB-ASSY AIR CLEANER	DEFORMED	446.30	446.30
1	CASE SUB-ASSY AIR CLEANER	SERVICEABLE	190.10	-
1	SEAL HOOD TO FRONT END PA	SERVICEABLE	24.40	-
1	COVER RADIATOR SUPP	SERVICEABLE	225.20	-
1	HORN ASSY LOW PITCHED	DEFORMED	112.70	112.70
1	HORN ASSY HIGH PITCHED	DEFORMED	112.70	112.70
1	GUIDE RADIATOR AIR NO.1 L	SERVICEABLE	58.20	-
1	GUIDE RADIATOR AIR NO.1 R	SERVICEABLE	54.00	-
1	SEAL RADIATOR TO SUPPORT	SERVICEABLE	24.40	-
1	COMPUTER SUB-ASSY ,HEADLAM	SERVICEABLE	481.40	-
1	COMPUTER SUB-ASSY ,HEADLAM	SERVICEABLE	481.40	-
1	SUPPORT RADIATOR UPPER LH	DEFORMED	76.10	76.10
1	SUPPORT RADIATOR UPPER RH	DEFORMED	76.10	76.10
1	AIR CLEANER FILTER ELEMEN	DEFORMED	63.70	63.70
2	BULB FOR FRT TURN SIGNAL	SERVICEABLE	20.00	-
1	COVER SUB-ASSY ENGINE UND	SERVICEABLE	178.20	-
1	COVER REAR BUMPER	DEFORMED	458.60	458.60
1	REINFORCEMENT SUB-ASSY RE	DENTED	318.80	318.80
1	GUARD -REAR BUMPER CENTER	DEFORMED	552.60	552.60
1	FILLER -REAR BUMPER EXTENS	SERVICEABLE	148.40	-
1	LENS AND BODY REAR LAMP L	CRACKED	548.40	548.40
1	COVER REAR BUMPER -TOW HOO	DEFORMED	82.70	82.70
1	ORNAMENT SUB-ASSY BACK DO	NECESSARY	45.80	45.80
1	PLATE -BACK DOOR NAME (HYB)	NECESSARY	52.40	52.40
1	PLATE -BACK DOOR NAME (PRI)	NECESSARY	60.80	60.80
1	GARNISH S.ASSY BACK DOOR	DEFORMED	881.70	881.70
1	PANEL SUB-ASSY BACK DOOR	DEFORMED	922.50	922.50
1	GLASS BACK WINDOW FIX	NECESSARY	720.90	720.90
1	GLASS BACK DOOR	NECESSARY	1,554.90	1,554.90
10	BUMPER PIECE	NECESSARY	22.00	22.00
1	LENS & BODY RR COMBINATIO	CRACKED	557.90	557.90
1	HOSE WATER BY-PASS (ADDITIONAL)	CUT	55.80	55.80

Report Ref No. CC3/CTI21010151/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SENSOR ASSY VACCUM (FOR E.F.I) (ADDITIONAL)	DEFORMED	390.00	390.00
1	CABLE ASSY HOOD LOCK CONTROL (ADDITIONAL)	DEFORMED	135.60	135.60
1	SUPPORT SUB-ASSY RADIATOR LH (ADDITIONAL)	DEFORMED	234.70	234.70
1	CLAMP (ADDITIONAL)	NECESSARY	15.00	15.00
1	HOSE CLAMP (ADDITIONAL)	NECESSARY	15.00	15.00
	LESS 25% DISCOUNT		-6,875.75	-5,750.20
			20,627.25	17,250.60
	<u>SPECIAL NETT ITEMS</u>			
1	VEHICLE NUMBER PLATE FRON (SN)	DEFORMED	50.00	50.00
1	REAR BOOT 65521111 CTPL (SN)	NECESSARY	30.00	30.00
1	REAR BONNET COMFORTDELGRO (SN)	NECESSARY	30.00	30.00
1	APP LOGO REAR BONNET CTPL(SN)	NECESSARY	40.00	40.00
1	REVERSE SENSOR ASSY (SN)	DEFORMED	135.70	135.70
1	BATTERY (SN)	DEFORMED	220.00	220.00
			505.70	505.70
	<u>LABOUR</u>			
	PANEL BEATING -FRT.		1,100.00	700.00
	SPRAYPAINT CHARGE.		800.00	500.00
	CHECK ALL LIGHTING.		50.00	20.00
	TUFF COAT ON AFFECTED PARTS.		50.00	40.00
	TO VAC & TOP UP A/C GAS.		120.00	30.00
	PANEL BEATING -REAR.		800.00	700.00
	SPRAYPAINT CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	40.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
	RENEW REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX RADIATOR ASSY. (ADDITIONAL)		100.00	80.00
	RENEW REAR WINDSCREEN GLASS. (ADDITIONAL)		120.00	120.00
	SPRAYPAINT FRT RH FENDER. (ADDITIONAL)		300.00	250.00
			4,340.00	3,040.00
GRAND TOTAL			25,472.95	20,796.30

Report Ref No. CC3/CTI21010151/Nea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			16,650.00
---	--	--	------------------

Report Ref No. CC3/CTI21010151/Nea3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7686H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7686H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7686H

RE-INSPECTION

