

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 01 Oct 2021

Preliminary Advice

Vehicle No	: SMA5637X	Accident Date	: 26/09/2021
Make	: HYUNDAI ELANTRA	Policy No.	: D19MPC0002723
Assignment Date	: 01/10/2021	Excess	: S\$0.00
Date of Inspection	: 01/10/2021	Est. Duration of Repair	: 14
Inspection At	: BLUWEL AUTOMOTIVE SERVICE PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6, #01-28/37/53/55/56 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,077.64
Revised Amount	:S\$	15,834.14
Check Items (Estimated)	:S\$	11,342.62
Total	:S\$	27,176.76

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	33,259.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,741.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$26,000.00 ON LUMP SUM BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.