



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

Date: 30-09-2021

India International Insurance Pte Ltd

64 Cecil Street

#04/06 IOB Building

Singapore 049711

Policy No.: D19MPC0002723-02

Vehicle No.: SMA5637X

Model: HYUNDAI ELANTRA

D.O.A 26/09/2021

Estimate Repair Cost For SMA5637X

NO.	DESCRIPTIONS	AMOUNT
1	1 PC FRONT RH HEADLAMP	\$ 1,198.00
2	1 PC FRONT RH HEADLAMP LOWER BRACKET	\$ 28.00
3	1 PC FRONT BUMPER	\$ 474.40
4	1 PC FRONT RH BUMPER FOG LAMP	\$ 266.00
5	1 PC FRONT RH BUMPER FOG LAMP COVER	\$ 115.40
6	1 PC FRONT RH BUMPER RETAINER	\$ 27.40
7	1 PC FRONT RH FENDER	\$ 1,227.70
8	1 PC FRONT RH FENDER INNER SHIELD	\$ 92.50
9	1 PC FRONT RH FENDER MUDFLAP	\$ 38.75
10	1 PC FRONT RH FENDER INNER GARNISH	\$ 68.80
11	2 PCS FRONT RH FENDER INNER SHIELD CLIPS	\$ 117.60
12	1 PC FRONT RH QUARTER FENDER COVER	\$ 40.50
13	1 PC FRONT RH FRONT DOOR	\$ 1,831.10
14	1 PC FRONT RH DOOR ROCKER PANEL	\$ 249.75
15	1 PC FRONT RH SIDE MIRROR ASSY	\$ 1,054.60
16	2 PCS FRONT RH DOOR HINGES (UPPER & LOWER)	\$ 97.40
17	1 PC FRONT RH DOOR CENTRE CATCH	\$ 66.20
18	1 PC FRONTRH DOOR OUTER HANDLE	\$ 179.10
19	1 PC FRONT RH DOOR OUTER CHROME MOULDING	\$ 74.60
20	2 PCS FRONT RH DOOR STICKERS	\$ 62.40
21	1 PC FRONT RH DOOR GLASS	\$ 240.50
22	1 PC FRONT RH DOOR GLASS INNER RUBBER SEAL	\$ 77.70
23	1 PC FRONT RH DOOR WEATHERSTRIP	\$ 72.30
24	1 PC FRONT RH DOOR INNER BOARD ASSY	\$ 487.95
25	1 PC FRONT RH DOOR REGULATOR GEAR	\$ 240.50
26	1 PC FRONT RH DOOR REGULATOR GEAR MOTOR	\$ 231.00
27	1 PC FRONT RH DOOR CONTROL UNIT SWITCH	\$ 185.40
28	1 PC FRONT RH DOOR PILLAR INNER RUBBER	\$ 118.70
29	1 PC FRONT RH ROCKER PANEL STEP GARNISH	\$ 40.21



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

NO.	DESCRIPTIONS	AMOUNT
30	PC FRONT RH DOOR INNER LOCK ASSY	\$ 194.20
31	1 PC FRONT RH DOOR PILLAR INNER GARNISH	\$ 78.80
32	1 PC REAR RH ROCKER PANEL STICKER	\$ 18.50
33	1 PC REAR RH DOOR STICKER	\$ 24.60
34	1 PC REAR RH DOOR PILLAR INNER RUBBER	\$ 118.70
35	1 PC REAR RH DOOR CENTRE CATCH	\$ 64.20
36	1 PC REAR RH DOOR	\$ 1,775.20
37	2 PCS REAR RH DOOR STICKERS	\$ 51.20
38	2 PCS REAR RH DOOR HINGES (UPPER & LOWER)	\$ 97.40
39	3 PCS REAR SEAT BELTS	\$ 1,889.94
40	3 PCS REAR SEAT BELTS CATCH	\$ 508.11
41	1 PC ROOF TOP INNER BOARD ASSY	\$ 847.90
42	1 PC ROOF TOP RH INNER BOARD AIR BAG	\$ 635.35
43	1 PC ROOF TOP LH INNER BOARD AIR BAG	\$ 635.35
44	2 PCS L&R SEAT BELTS ASSY	\$ 1,461.40
45	2 PCS L&R SEAT BELTS CATCH	\$ 498.74
46	1 PC FRONT RH SEAT ASSY WITH AIR BAG	\$ 2,336.56
47	1 PC SRS UNIT ASSY	\$ 148.48
48	1 PC ECU UNIT ASSY	\$ 478.70
49	1 PC FRONT RH SHOCK ABSORBER	\$ 372.50
50	1 PC FRONT RH SHOCK MOUNTING	\$ 126.90
51	1 PC FRONT RH SHOCK ABSORBER BEARING	\$ 81.90
52	1 PC FRONT RH SHOCK ABSORBER RUBBER	\$ 35.30
53	1 PC FRONT RH SHOCK ABSORBER STOPPER	\$ 31.40
54	4 PCS FRONT RH ENGINE MOUNTINGS	\$ 224.25
55	1 PC FRONT RH LOWER ARM	\$ 296.80
56	1 PC FRONT RH KNUCKLE ARM	\$ 363.60
57	1 PC FRONT RH KNUCKLE ARM BEARING	\$ 452.80
58	1 PC FRONT POWER STEERING RACK PINION ASSY	\$ 1,214.70
59	1 PC FRONT RH TIE ROD ASSY	\$ 1,214.70
60	1 PC FRONT STAY BAR	\$ 209.10
61	1 PC FRONT RH LINKER BAR (LOWER)	\$ 60.45
62	1 PC FRONT RH DISC ROTOR	\$ 194.25
63	1 PC FRONT RH BRAKE CALIPER PIPE HOUSE	\$ 101.70
64	1 PC FRONT RH SPORT RIM	\$ 600.00
65	1 PC FRONT RH TYRE	\$ 300.00
66	1 PC FRONT WIPER TANK ASSY	\$ 66.30
67	1 PC FRONT SUPPORT PANEL	\$ 949.30



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

NO.	DESCRIPTIONS	AMOUNT
68	1 PC FRONT ENGINE COVER UNDERCARRIAGE	\$ 133.30
		\$ 27,897.04
	LESS 20%	\$ (5,579.40)
		\$ 22,317.64
	<u>MISC & LABOUR CHARGES</u>	
69	TOWING	\$ 150.00
70	REMOVE & REFIX FRONT W/SCREEN	\$ 150.00
71	REMOVE & REFIX FRONT ENGINE ASSY	\$ 500.00
72	REMOVE & REFIX FRONT UNDERCARRIAGE	\$ 700.00
73	REMOVE & REFIX FRONT DASHBOARD	\$ 500.00
74	REMOVE & REFIX FRONT & REAR SEAT BELTS,SRS UNIT,ECU UNIT, ROOF BOARD & AIR BAG	\$ 800.00
75	REMOVE & REFIX PARTS, WELDING, CUT, JACK CHASSIS FRAME & ALIGNMENT	\$ 3,000.00
76	REMOVE AIR CON & REFILL AIR CON GAS	\$ 120.00
77	RESPRAY WHOLE RH SIDE (INSIDE & OUTSIDE). TOUCH-UP.	\$ 2,800.00
78	ELECTRICAL & FOCUS WIRING	\$ 120.00
79	SRS & ECU COMPUTER RESETTING	\$ 800.00
80	COMPUTERISE & WHEELS ALIGNMENT	\$ 120.00
		\$ 9,760.00
	TOTAL:	\$ 32,077.64