

TP ALG
Xiao Chen.

GBA1196T. 2007 Oct.
Toyota Dyna. 2982cc

JTFAT35YX03001240.

Front Number Plate	NE new	30(SN) +
Front Bumper	Rep	589.40 +
Front Bumper Reinforcement	MP	450.20 +
Front Grille	Cruld	564.10 /
Front Grille clips.	new	20(SN) /
Headlamp x 02	Cruld	646.1 x 2 = 1292.20 /
Front Panel	Rep	1019.50 +
Front Panel Toyota Logo	new	65.90 /
Front Panel Dyna Wordings	new	79.20 /
Front RH Corner Panel Distal	new	264.30 /
Front RH Corner Panel Top Garnish	cut	122.70 /
Front RH Door	Rep	1310.80 +
Front RH Door Company Address Stickers	new	30(SN) /
Front RH Door Advertisement Stickers	new	300(SN) /
Front Wiper Panel Side Garnish RH.	new	150(SN) /
	Cruld	195.50 /

2584.30

1938.22

S-X: 200

GBA7196T.

Panel Beating.

~~1000~~ 500.

Spray Painting.

1000 850

Wiring.

~~50~~ 30

To remove front windscreen

180 +

To transfer front door fittings.

150. x.

1380.

total: 3518/23

L/S: 2.8k.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: