

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21010154/KUCE2

**Date:** 19/11/2021

### REFERENCE

Insured/Claimant: Zhou Jing Policy No: DMPCSNW00188342000

Date of Loss: 26/09/2021 Nature of Claim: OD

Claim No: SNM21D205477/C01/TANKW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY7775L**

Make & Model: JAGUAR XJ, 2.0 TSS (A)

Reg. Date: 28/11/2014 (Man. Year: 2014)

Colour: Metallic Dark Brown

Engine Capacity: 1999 cc

Market Value/New Car Price: S\$105,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 040614030500204PT

Chassis No: SAJAC12M4FPV77648

Odometer: 109657 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45ZR19

Front Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Tyre Size: 275/40ZR19

Rear Left Side: Pirelli 8 mm

Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,886.00	16,925.00	5,961.00	26.05
Miscellaneous Items	955.00	525.00	430.00	45.03
Labour	646.80	541.80	105.00	16.23
Paintwork Labour	1,142.01	850.38	291.63	25.54
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,629.81</b>	<b>18,842.18</b>	<b>6,787.63</b>	<b>26.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>14,900.00</b>		
<b>(S\$)</b>	25,629.81	14,900.00	10,729.81	41.86
<b>+ GST 7.00/7.00% (S\$)</b>	1,794.09	1,043.00	751.09	41.86
<b>Nett Amount (S\$)</b>	<b>27,423.90</b>	<b>15,943.00</b>	<b>11,480.90</b>	<b>41.86</b>

### INSPECTION

Date of Assignment: 01/10/2021 Present Location:

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 01/10/2021 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 8.0 days

**Adjuster:** KENNETH KONG

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2021)
Parts:	143	JAGUAR XJ 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY7775L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		22,886.00 F	*16,925.00 F
F=Franchise part.						
Total Parts (S\$)					22,886.00	16,925.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	955.00	525.00
Sub Total (\$\$)			955.00	525.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	1,142.01	850.38
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	646.80	541.80
Gross Labour Cost (\$\$)			1,788.81	1,392.18

Report was unsubmitted during this print-out.

< END OF ESTIMATES >