

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Billy Tan

Date: 05 Oct 2021

Preliminary Advice

Vehicle No	: SGY7775L	Accident Date	: 26/09/2021
Make	: JAGUAR XJ	Policy No.	: DMPCSNW00188342000
Assignment Date	: 01/10/2021	Excess	: S\$0.00
Date of Inspection	: 01/10/2021	Est. Duration of Repair	: 8
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,629.81
Revised Amount	:S\$	16,369.41
Check Items (Estimated)	:S\$	9,045.00
Total	:S\$	25,414.41
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	85,419.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,581.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer able to undertake the repair cost not more than \$19K on lumpsum basis