



## Inspection Services Pte Ltd

Date : 03 December 2020

To : **Kennedys Legal Solutions**  
80 Raffles Place  
#44-01 UOB Plaza 1  
Singapore 048624

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road  
#08-08, Cendex Centre  
Singapore 169208  
Tel: +65 6255 0808  
Fax: +65 6849 9155  
[info@ajaxinspection.com](mailto:info@ajaxinspection.com)

Invoice No – **AV26873**  
Company Reg No -201318067R  
GST Reg No - 201318067R

### TAX INVOICE

YOUR REF / CLAIM NUMBER : PYK1/JO1/961922.Income(2857)  
OUR REF : AVS2017-12762/WH  
TP VEHICLE NO : FBL1182P  
CLAIM TYPE : PRE-REPAIR SURVEY  
DATE OF SURVEY : 06 October 2017

No.	Description	Amount (\$\$)
1	Professional fee	100.00

Subtotal 100.00  
GST 7.00% 7.00  
**Total 107.00**

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: [accounts@ajaxadjusters.com](mailto:accounts@ajaxadjusters.com)

### AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R

**PRE-REPAIR SURVEY REPORT**

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Yon Kai Jie

<b>Assign Date:</b>	06/10/2017	<b>Survey Date:</b>	06/10/2017	<b>Our Ref:</b>	AVS2017-12762/WH
<b>Accident Date:</b>	26/09/2017	<b>TP Policy No:</b>	NA	<b>Your Ref:</b>	MT/0963221-003
<b>Place of Survey:</b>	Equator Brotherhood 25 Kaki Bukit Road 4 #03-79 Synergy @ KB Singapore 417800			<b>Claim Type:</b>	Third Party
				<b>Claimant:</b>	Muhammad Zulhakim Bin Bakar

**Description of Vehicle:**

<b>Veh. No:</b>	FBL1182P	<b>Make/Model:</b>	Honda CBR1000RR Fireblade
<b>Colour:</b>	Multi-colored	<b>Engine No:</b>	SC59E2508627
<b>Engine Capacity:</b>	999cc	<b>Chassis No:</b>	JH2SC59A4GK800458
<b>Odometer:</b>	8902	<b>Reg. Date:</b>	09/10/2016

**Condition of Vehicle:**

<b>General:</b>	Average	<b>Modification:</b>	No	<b>Steering:</b>	NA
<b>Handbrake:</b>	NA	<b>Footbrake:</b>	NA	<b>Paint work:</b>	Good
<b>Tyre Make:</b>	Bridgrstone				
<b>Front Tyre Size:</b>	120/70/R17	<b>Front Side:</b>	4mm		
<b>Rear Tyre Size:</b>	195/50/R17	<b>Rear Side:</b>	4mm		

**Description of Damage:**

The vehicle sustained damage on the front, rear and right portions.

The exhaust pipe, front fairing, engine cover, headlamp cowling, front mudguard and handle bar were among the items affected.

**Remarks:**

Our recommended amount for the cost of contract lumpsum repair is S\$1,800.00 with approximately four (4) working days to complete. However, no finalisation was agreed with the repairer.




COMPLETED 01 DEC 2020

**Adjuster:** Liew Kong Ho on behalf of Lee Wee Ho  
Motor Appraiser

Date

*Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.*

Adjustment of Repair Cost for Vehicle:			FBL1182P	Our Ref: AVS2017-12762/WH	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Honda swing arm	Not necessary	2,000.00	--
2	2	Honda front brake disc @ \$400.00	Not necessary	800.00	--
3	2	Honda front fork @ \$1,700.00	Repair	3,400.00	--
4	1	Honda tripple clamps (top)	Not necessary	300.00	--
5	1	Honda tripple clamps (bottom)	Not necessary	700.00	--
6	1	Hona steering cone bearing	Not necessary	140.00	--
7	1	Honda rear suspension	Not necessary	1,700.00	--
8	1	Honda suspension linkage set	Repair	--	--
9	1	Honda headlight set	Not necessary	1,450.00	--
10	1	Honda head fairing	Not consistent	800.00	--
11	1	Honda mirror (right)	Grazed	300.00	300.00
12	1	Honda rider footrest bracket (right)	Not necessary	150.00	--
13	1	Honda rider footrest (right)	Damaged	90.00	90.00
14	1	Honda clutch case	Cut	350.00	350.00
15	1	Honda clutch gasket	Necessary	20.00	20.00
16	1	Honda bar end balancer (right)	Grazed	25.00	25.00
17	1	Honda brake lever	Grazed	70.00	70.00
18	2	Honda front wheel bearing @ \$35.00	Not necessary	70.00	--
19	2	Honda rear wheel bearing @ \$35.00	Not necessary	70.00	--
20	1	Honda swing arm bushing set	Not necessary	80.00	--
21	1	Honda swing arm shaft	Not necessary	120.00	--
22	1	Honda handle bar (right)	Bent	200.00	200.00
23	1	Rozima crash slider	Grazed	180.00	180.00
24	1	Zero gravity windshield (front)	Not consistent	230.00	--
Sub Total:				13,245.00	1,235.00
Discount (less 10% ):				1,324.50	123.50
				11,920.50	1,111.50

### Special Nett Items

1	3	Motul 300V engine oil @ \$30.00	Necessary	90.00	80.00
---	---	---------------------------------	-----------	-------	-------

**Note:** This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



## Inspection Services Pte Ltd

<b>Adjustment of Repair Cost for Vehicle:</b>			<b>FBL1182P</b>	<b>Our Ref:</b> AVS2017-12762/WH	
<b>No.</b>	<b>Qty</b>	<b>Description of Parts</b>	<b>Condition</b>	<b>Repairer's Estimate S\$</b>	<b>Our Recommendation S\$</b>
2	1	Rear number plate	Bent	15.00	15.00
3	1	Bodis twin exhaust (Approved)	Repair	2,850.00	--
<b>Sub Total:</b>				2,955.00	95.00
<b>Total Parts Price:</b>				14,875.50	1,206.50

Labour Cost			
1	To remove & replace swing arm, rear suspension, front & rear wheel bearing, axle shaft, front fork, tripple clamps, steering cone, front brake disc.	480.00	--
2	To remove & replace above body damaged parts and check lighting system.	500.00	400.00
3	To respray paint on the affected area.	1,200.00	600.00
4	To conduct chasss aligment.	280.00	--
5	To remove and repair, balancing and respray.	280.00	--
6	Towing - from traffic police compound to workshop.	35.00	35.00
7	Towing - (2 way trip workshop to accident reporting)	70.00	70.00
8	Exhaust inspection.	95.00	--
Sub Total:		2,940.00	1,105.00
Grand Total:		17,815.50	2,311.50

**Note:** This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

### AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R