

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

Steve (LKk)
 4/10/21
 w/p, L/S
 Respray After Spray

4 days

INS: INDIA INTERNATIONAL INSURANCE PTE LTD
 COMPANY: CK TRANSPORT & TOUR PTE LTD
 Vehicle Registration no. : PA 6982 G / ISUZU LT 134 P
 DOA: 30/9/2021

Date : 4-Oct-21 Quotation No. : 30096982

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear Bumper BR		\$2,800.00	1750-
2	2	Rear Bumper side Bracket BT	100-650 x 2	\$1,300.00	200-
3	1	Rear bumper bim x m		\$880.00	
4	1	Rear bumper inner reinforcement BT		\$868.00	500-
5	1	Rear inner central panel bracket BT (chassis)		\$1,550.00	350-
6	1	Rear Engine Compartment Cover with grille x m		\$3,350.00	
7	1	Rear Engine Compartment Cover -Interlock x m		\$365.00	
8	1	Rear Engine Compartment Cover - outer handle x m		\$198.00	
9	1	Rear Engine Compartment Cover - inner frame x m		\$580.00	
				<u>\$11,891.00</u>	2800
				Less 10%	-10%
				<u>\$-1,189.10</u>	
				Sub-total	2510
				\$10,701.90	

SPECIAL NETT ITEMS

1	1	Rear Number Plate CUT	\$65.00	45-
2	1	Rear 60km/H Sticker dec	\$30.00	25-
3	2	Rear no plate lamp BR	\$138.00	100-
			\$233.00	170

LABOUR & MISC CHARGES

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$1,500.00	600
2	Supply spray paint material (multi purpose color) and necessary items to respray on accident damage area.	\$950.00	850

1450

TOTAL	\$2,450.00
Total Parts and Labour Cost of Repair	\$13,384.90

= 4140
 L/S- 3312
 = 3300