

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

Yr Regn:

OD / P / WS / TP RES / OD RES / EVA / INV / MVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Sur / STD A/Rim or

Tyre Size:

F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) _ S + RS _ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SI involved 17A9 713
acc date 31-3-2024 NR4 4287



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 39221

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING
78 SHENTON WAY
#07-16

SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPT

DATE : 29/09/2021
CLAIM NO. : 11800
POLICY NO. : MC/00931333

FROM : RAYMOND

VEHICLE NO. : FZ2045A
MAKE/MODEL : YAM / FZ6S

*Not Authorised
1/10/21
1/58
photo attached.*

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY REAR - (REPORTED BY MECHANIC)	Repair	1.00	\$525.00	11x 525.00
2	BALANCER HANDLE (MOTOVATION) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$143.00	SC 143.00
3	BEARING SWING ARM P/N: 53803 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$33.00	66.00 ?
4	BELLY PAN (PUIG) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$510.00	100 510.00
5	BODY FRONT UPPER 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$191.00	Cre 191.00
6	BOX REAR (KAPPA) KGR52 P/N: 60855 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$600.00	Pged 600.00
7	BRACKET 6 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	Rec 41.00
8	BRACKET BOX REAR (MONORACK) P/N: 34794 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$330.00	Sent 330.00
9	CLAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.50	NR 4.50

*39221 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

bizSAFE₃



Address: No. 6, DeFu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2003-14083
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	CLAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
11	CLAMP WIRE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00
12	COVER REAR FENDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	73.00
13	COVER REAR FENDER 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
14	DAMPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50
15	DAMPER 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.50	4.50
16	DAMPER 2 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$1.50	3.00
17	EMBLEM 1 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$9.00	18.00
18	FOOTREST FRONT RH P/N: 38769 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$52.00	52.00
19	FOOTREST REAR 2 P/N: 57543 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
20	GUIDE MUDGUARD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00
21	HANDLE BAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	73.00
22	HANDLE SEAT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$380.00	380.00 X
23	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	10.00	\$63.00	630.00
24	LAMP SIGNAL FRONT RH P/N: 70995 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$111.00	111.00

*39221 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
25	LEVER BRAKE P/N: 40147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$112.00	5.02 112.00 ✓
26	LIGHT LICENSE PLATE P/N: 57814 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$95.00	39.0 95.00 ✓
27	MUDFLAP REAR P/N: 32626 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	2. 45.00 ✓
28	MUFFLER (AKRAPOVIC) ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,052.00	? 2,052.00
29	PEDAL, BRAKE P/N: 70220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$95.00	4.07 95.00 ✓
30	PLUG - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	? 10.00
31	PULLER CHAIN 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	? 20.00
32	REAR FLASHER LIGHT ASSY 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	0.00 63.00 ✓
33	REAR FLASHER LIGHT ASSY 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	? 63.00
34	REAR VIEW MIRROR ASSY (RIGHT) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$111.00	4.07 111.00 ✓
35	REFLECTOR REAR (RED) P/N: 32627 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	3.00 18.00 ✓
36	REPAIR ON SWINGARM - (REPORTED BY MECHANIC)	Repair	1.00	\$60.00	Repair 1.00 60.00 X
37	RIVET - (REPORTED BY MECHANIC)	REPLACE	2.00	\$1.50	? 3.00
38	RUBBER FOOTREST FRONT P/N: 34783 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	0.07 22.00 ✓
39	SEAL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.00 1.50 ✓

*39221 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	SEAL 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.50	4.50
41	SEAL 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
42	SHAFT SWINGARM P/N: 54031 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$69.00	69.00
43	SIDE COVER ASSY 1 P/N: 70218 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
44	SIDE COVER ASSY 2 P/N: 70221 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
45	SLIDER FRAME (MOTOVATION) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$126.00	126.00
46	SPARY PAINT ON HANDLE SEAT - (REPORTED BY MECHANIC)	Spray	1.00	\$84.00	84.00
47	SPRAY PAINT ON BODY FRONT UPPER 1 - (REPORTED BY MECHANIC)	Spray	1.00	\$165.00	165.00
48	SPRAY PAINT ON SIDE COVER ASSY 1 - (REPORTED BY MECHANIC)	Spray	1.00	\$90.00	90.00
49	SPRAY PAINT ON SIDE COVER ASSY 2 - (REPORTED BY MECHANIC)	Spray	1.00	\$90.00	90.00
50	SPRAY PAINT ON WINDSHIELD - (REPORTED BY MECHANIC)	Spray	1.00	\$50.00	50.00
51	STAY FLASHER 1 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$1.50	3.00
52	TRIM - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	16.00
53	WASHER THRUST SWINGARM P/N: 53809 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$19.00	38.00
54	WINDSHIELD (PUIG) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$300.00	300.00

SUB TOTAL
GST @ 7 %

\$7,727.00
\$540.89

*39221 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
GRAND TOTAL (SGD)					\$8,267.89

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39221 *

bizSAFE₃



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	395J
Vehicle Details	
Vehicle No.:	FZ2045A
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2021
Vehicle Make:	YAMAHA
Vehicle Model:	FZ6S
Primary Colour:	Blue
Secondary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	J507E061713
Chassis No.:	JYARJ071000035866
Maximum Power Output:	-
Open Market Value:	\$7,931.00
Original Registration Date:	09 May 2005
First Registration Date:	09 May 2005
Transfer Count:	7
Actual ARF Paid:	\$1,190.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$2,474.00
COE Rebate Amount:	\$713.00
Total Rebate Amount:	\$713.00

The information contained herein is correct as at 01 Oct 2021

OK



Singapore's Digital Future

Discover the Key Benefits of an Interconnected Digital Infrastructure. Get the Whitepaper. Equinix

[LEARN MORE](#)


Bike model

yamaha fz6

Search

Type Of Vehicle

Any



Price From

Any



Price To

Any



Class

Any



More Search Options ▾

Sort By

Sort By

Recommended ▾



Yamaha FZ6-S

Reg Date : 20/01/2005

Capacity : 600cc

Vehicle Type : Street Bikes

Mileage : -

Posted on : 01/09/2021

SGD \$5500

★ Paid Ad

★ Dealer Ad

Details >



Yamaha FZ6-S

Reg Date : 25/05/2004

Capacity : 600cc

Vehicle Type : Street Bikes

Mileage : 80000km

Posted on : 31/08/2021

SGD \$4800

★ Paid Ad

★ Dealer Ad

Details >

Yamaha FZ6-S

Registration Date	20/01/2005
COE Expiry Date	29/02/2024 (2 years 4 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes
	SGD \$5500

Yamaha FZ6-S For Sale.

Downpayment \$500 Or \$0 Without Insurance (Terms And Conditions Apply).

Pls Drop By De Xing Motor Pte Ltd For Quotation

We Will Give You The Best Pricing Quote And Any Information You Need
Read more 

Similar Bikes

[View More](#)

08/09/2021

Used Bike

★ Direct Seller

Yamaha FZ6-S

Good Condition Yamaha FZS600...

\$5000

31/08/2021

Used Bike

★Speedway Motor Pte ...

Yamaha FZ6-S

Used Yamaha FZ-6 For Sales ...

\$4800