Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 08 Nov 2021 Jacqueline Tan Date:

Preliminary Advice

Insured Vehicle No : SML9155K

TP Vehicle No : SJS2667U Accident Date : 29/09/2021 Make : HYUNDAI HD AVANTE 1.6 A (BI-FUEL) **Assignment Date** : 03/10/2021

Date of Inspection : 04/10/2021 Est. Duration of Repair : 7

Inspection At : TEAM AUTOPRO PTE LTD (SIN MING)

385 SIN MING DRIVE, #01-02 VICOM INSPECTION CENTRE

SINGAPORE 575718

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,885.12
Revised Amount	:S\$	6,065.57
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,065.57
Lump Sum Repair	:S\$	4,850.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylk
	let us have your authorisation.	

(The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		0, ,	110 11100	

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.