

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21010171/GUF3N2**Date:** 16/11/2021REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC21A00038400
Claimant Vehicle No :	SHC1105P	Insured Vehicle No :	SJT5625R
Date of Loss:	30/09/2021	Nature of Claim:	TP
		Claim No:	DMPC2100346H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1105P		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS055792
Reg. Date:	05/07/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU303561189
Colour:	Blue	Odometer:	461735 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,343.40	2,147.57	195.83	8.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,140.00	590.00	34.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,073.40	3,287.57	785.83	19.29
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	4,073.40	2,650.00	1,423.40	34.94
+ GST 7.00/7.00% (S\$)	285.14	185.50	99.64	34.94
Nett Amount (S\$)	4,358.54	2,835.50	1,523.04	34.94

INSPECTION

Date of Assignment:	01/10/2021	
Date Inspected:	01/10/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1105P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	10		*BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*GUARD-REAR BUMPER CENTER	Deformed	552.60 FL	*552.60 FL
4	1		*REINFORCEMENT SUB-ASSY RE	Bent	318.80 FL	*318.80 FL
5	1		*GARNISHS ASSY BACK DOOR	Cut	881.70 FL	*881.70 FL
6	1		*COVER REAR BUMPER-TOW HOO	Scratched	82.70 FL	*82.70 FL
7	1		*FILLER-REAR BUMPER EXTENS	Not Necessary	148.40 FL	*- FL
8	1		*RETAINER RR BUMPER SIDE R	Not Necessary	112.70 FL	*- FL
9	1		*PLATE-BACK DOOR NAME (HYB)	Necessary	52.40 FL	*52.40 FL
10	1		*PLATE-BACK DOOR NAME (PRI)	Necessary	60.80 FL	*60.80 FL
11	1		*ORNAMENT SUB-ASSY BACK DO	Necessary	52.90 FL	*52.90 FL
12	1		*REAR BOOT 65521111 CTPL	Necessary	30.00 FS	*30.00 FS
13	1		*REAR BONNET COMFORTDELGRO	Necessary	30.00 FS	*30.00 FS
14	1		*APP LOGO REAR BONNET CTPL	Necessary	40.00 FS	*40.00 FS
15	1		*REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
16	1		*BUMPER PROTECTOR MAT	Deformed	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,029.30	2,768.20
- List Item Discount on L Items 25.00/25.00% (S\$)	685.90	620.63
Total Parts (S\$)	2,343.40	2,147.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	RENEW ADVERTISEMENT STICKER	New	50.00	50.00
4	RENEW ADVERTISEMENT STICKER	New	200.00	200.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
Gross Labour Cost (\$)			1,730.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >