



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2108962

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 30/12/2021
Reference CC4/LPC21010176/Eea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 7631Y
Insured Veh. XD 5663Z
Claim No. 21/21/21/VC05/025001
Policy No. Z21VC05006923
Accident Date 01/10/2021
Inspection Date 04/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21010176/Eea3q2 Date: 30/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5663Z	Veh. Inspected	SHC 7631Y	
Policy No.	Z21VC05006923	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/025001	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	01/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVKU164737	Colour	YELLOW	
Odometer	301662 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	4 mm	
L/H Front Tyre	195/65 R15	SAILUN	4 mm	
R/H Rear Tyre	195/65 R15	SAILUN	4 mm	
L/H Rear Tyre	195/65 R15	SAILUN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/10/2021	Inspection Date	04/10/2021	
Survey held at	DING AUTOMOTIVE PTE LTD 10 SECTOR C SIN MING INDUSTRIAL EST, #01-20, SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7631Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH SIDE MIRROR ASSY	BROKEN	1,054.60	1,054.60
1	FRONT LH DOOR PANEL	TO REPAIR SEE LABOUR	1,978.00	-
1	FRONT LH DOOR FRAME UPPER BLACK TAPE	NOT NECESSARY	16.60	-
1	FRONT LH DOOR REAR BLACK TAPE	NOT NECESSARY	9.90	-
1	FRONT LH OUTER DOOR BELT MOULDING ASSY	NOT NECESSARY	73.50	-
1	FRONT LH OUTER DOOR HANDLE	NOT NECESSARY	168.90	-
1	FRONT LH SIDE MIRROR COVER	BROKEN	40.60	40.60
1	FRONT LH SIDE MIRROR GLASS	NOT NECESSARY	175.90	-
	LESS 20% DISCOUNT		-703.60	-219.04
			2,814.40	876.16
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR 'COMFORT DELGRO' STICKER (SN)	NECESSARY	140.00	80.00
1	FRONT DOOR MOULDING CLIP (SN)	NOT NECESSARY	50.00	-
			190.00	80.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF FRONT LH DOOR PANEL .		800.00	100.00
	TO RUST PROOFING OF THE ACCIDENT AREA.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO TRANSFER OF FRONT DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	220.00	-
	TO DIAGNOSTIC ,CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE.	NOT NECESSARY	260.00	-
	TO RESPRAY FRONT DOOR PANEL .		250.00	200.00
	TO RESPRAY FRONT DOOR OUTER HANDLE AND COVER.	NOT NECESSARY	250.00	-
	TO RESPRAY FRONT SIDE MIRROR .		250.00	80.00
			2,500.00	380.00
	GRAND TOTAL		5,504.40	1,336.16

Report Ref No. CC4/LPC21010176/Eea3q2



RECOMMENDED COST OF REPAIRS			1,336.16
-----------------------------	--	--	-----------------

Report Ref No. CC4/LPC21010176/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7631Y

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7631Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7631Y

RE-INSPECTION

