

ASS. REC. BY:

REF: CS

AIS / 210101771Ku f3e2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: ER 5005A

at Workshop m/s

Optims

of

6468

Insured:

Policy No. SP2000085397-01

Claims No. 2021 20002869-GK

Sum Insured: Excess: \$20000 ?


(Client's Record)

Make of Veh:

1pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$1,250,000

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

ER 5005A

Yr Regn:

11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Rolls Royce

C.C.

6789

Colour

M.P. Blue / White

A/C:

Insured / Std / NI / NA

Sp. Reading

32273

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SCA 687 P08KU T03131

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

255 / 45R 22

R:

255 / 40R 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continued

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

28/9/21

D.O.I.

4/10/2021

Survey held at

Des. of Damages (Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Spare parts, needs to order from over sea, will be delay in repair

Confirmed P/P \$100,075; 10 repair days

(RED \$59064; 37%)

NOTE: Please submit report through email. Email address is claims@allianz.com.sg.

Date/Time, File Pass to?

☐

: Prell. Report

1) 3/11 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S - RS. \$

Fees

Others

TOTAL

Report Format:

OD

Lump Sum / I.B.I: (\$ 100,075

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	646B
Vehicle Details	
Vehicle No.:	ER5005A
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2021
Vehicle Make:	ROLLS ROYCE
Vehicle Model:	PHANTOM AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	90233191N74B68A
Chassis No.:	SCA687S08KU103131
Maximum Power Output:	420.0 kW (563 bhp)
Open Market Value:	\$419,930.00
Original Registration Date:	09 Nov 2018
First Registration Date:	02 Nov 2020
Transfer Count:	0
Actual ARF Paid:	\$727,874.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Nov 2028
PARF Rebate Amount:	\$545,905.00
Intended COE Rebate Details	
COE Expiry Date:	01 Nov 2030
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,889.00
COE Rebate Amount:	\$36,200.00
Total Rebate Amount:	\$582,105.00

The information contained herein is correct as at 04 Oct 2021

OK

Date : 03.10.2021
Vehicle No: ER5005A
Model: ROLLS ROYCE PHANTOM AUTO
Chassis: SCA687S08KU103131
Reg.Year: 2020
Policy No: SP20005397-01
Date of Accident: 28.09.2021

TO MOTOR CLAIM DEPT
Allianz Insurance

SINGAPORE PTE LTD

79 Robinson Road #09-01

SINGAPORE 068897

*Not Asst
Resumy B4 painting
Ex TBA*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		TA \$12,500.00
2	FRONT BUMPER TOW COVER	1		\$100.00
3	FRONT BUMPER GRILLE	1		\$820.00
4	FRONT BUMPER LOWER CHROME	1		RM/LG \$3,800.00
5	FRONT BUMPER GRILLE CHROME LH	1		RM \$1,950.00
6	FRONT BUMPER GRILLE CHROME RH	1		\$1,950.00
7	FRONT SPONGE	1		\$450.00
8	FRONT REINFORCEMENT	1		\$3,200.00
9	FRONT GRILLE LOWER BRACKET	1		DRY \$490.00
10	FRONT LICENSE CHROME GARNISH	1		BR \$2,150.00
11	SUPPORT TOP COVER	1		\$1,200.00
12	FRONT AIR GUIDE	1		CM \$1,750.00
13	FRONT LOWER AIR GUIDE	1		\$1,150.00
14	FRONT FENDER LH	1		\$16,000.00
15	FRONT FENDER RH	1		CM \$16,000.00
16	HEADLAMP LH	1		\$12,850.00
17	HEADLAMP RH	1		\$12,850.00
18	FRONT RADIATOR GRILLE	1		RM \$9,100.00
19	FRONT RR EMBLEM	1		RM \$580.00
20	FRONT RR ORNAMENT(SPIRIT OF ECSTASY)	1		\$16,135.00
21	FRONT RADIATOR AIR DUCT LH	1		\$960.00
22	FRONT RADIATOR AIR DUCT RH	1		\$960.00
23	FRONT PARKING SENSOR	4	2 \$500.00	\$2,000.00
24	FRONT PARKING SENSOR SEAL	4	\$100.00	\$400.00
25	NIGHT VISION FRONT CAMERA	1		\$6,400.00
26	CAMERA HOLDER	1		\$265.00
27	CAMERA BRACKET	1		\$100.00
28	ORNAMENT RETRACT MECHANISM	1		\$5,050.00
29	ORNAMENT COVER PANEL	1		\$1,080.00
30	BONNET	1		REPAIR
SUB TOTAL				\$132,240.00
COST +10%				\$13,224.00
PARTS TOTAL				\$145,464.00

Head office

6 Kang Chong Road Singapore 159143
Tel: (+65) 6472 1212 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date : 03.10.2021
 Vehicle No: ER5005A
 Model: ROLLS ROYCE PHANTOM AUTO
 Chassis: SCA687S08KU103131
 Reg.Year: 2020
 Policy No: SP20005397-01
 Date of Accident: 28.09.2021

TO MOTOR CLAIM DEPT
Allianz Insurance
SINGAPORE PTE LTD
 79 Robinson Road #09-01
 SINGAPORE 068897

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	Front license plate	1		nec \$75.00 ✓
1	FRONT FENDER CUSTOMIZED PAINT STRIPE LH	1		m \$1,500.00 ✓
1	FRONT FENDER CUSTOMIZED PAINT STRIPE RH	1		m \$1,500.00 ✓
1	COOLANT	1		\$200.00 ?
S/N TOTAL				\$3,275.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR AT FRONT ACCIDENT AREA.

1600l \$3,000.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ADCCIDENT AREA.

2100l \$5,000.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

u2 \$450.00 x

TO CHECK WIRING & ELECTRONIC SYSTEM ETC.

\$300.00 801

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$300.00 7

TO RE-PROGRAMME FRONT SENSORS.

\$350.00 7

TO RE-PROGRAMME HEADLAMPS.

\$1,000.00 7

LABOUR TOTAL \$10,400.00

TOTAL \$159,139.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/09/2021 15:05 (SGT)
Date of Accident	28/09/2021 17:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	FORMER HALLPIKE ST
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	ER5005A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	RAJ KUMAR S/O NARAIN DAS
NRIC No	S0207646B
Email Address	saleha@rbgroup.com.sg
Mobile Phone No	(Phone) +65-97586067
Alternative Phone No	+65-97586067

VEHICLE PARTICULARS

Manufacturer	Rolls Royce
Model	Phantom
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	6749


INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SP2000085397-01
Cover Note Number	02/11/2020 - 01/11/2021

DRIVER

Name of Driver	MOHAMED ISHAK SADHIK ALI
Passport No/FIN	G5405927U

Sketch Plan



FORMER HALLWAY STREET
(A) ER5005A (1PKEP)
(B) SJU3557L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/09/2021 at about 5.50pm, I informed Isahak Saadik Ali (Fin. GS4059 2761) was about to drive off my boss, Mr Rajkumar S/O Naraindas (SD2076468) Rolls Royce Phantom car (ER5005A) from the private parking lot 75 High Street and was waiting to see any oncoming car coming from the right side of the road. Mr Ngok Chia See (SO187565E) who was driving Toyota Ahi (SJU3557L) didn't see my car waiting on the left to come out and hit against the front port of my car. We both went to the River Valley Neighbourhood police post at Delta Avenue to report the incident. The police noted our particulars and that we exchanged our particulars. Mr Ngok Chia See had admitted his fault of not seeing my car on the left and that he had hit against my car.

I'm making this report to make a third party claim against insurer of Mr Ngok Chia See.

TP claim @ optima werkz

[Signature]
30/09/21