

Date: 03.10.2021
Vehicle No: ER5005A
Model: ROLLS ROYCE PHANTOM AUTO
Chassis: SCA687S08KU103131
Reg. Year: 2020
Policy No: SP20005397-01
Date of Accident: 28.09.2021

TO MOTOR CLAIM DEPT
Allianz Insurance
SINGAPORE PTE LTD
79 Robinson Road #09-01
SINGAPORE 068897

*Not Ashair
Resumy Bk paint
Ex TRA*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT	S\$	AMOUNT S\$
1	FRONT BUMPER	1			<i>Tr</i> \$12,500.00
2	FRONT BUMPER TOW COVER	1			<i>Red</i> \$100.00
3	FRONT BUMPER GRILLE	1			<i>CRT</i> \$820.00
4	FRONT BUMPER LOWER CHROME	1			<i>Red/Cut</i> \$3,800.00
5	FRONT BUMPER GRILLE CHROME LH	1			<i>Red</i> \$1,950.00
6	FRONT BUMPER GRILLE CHROME RH	1			<i>Red</i> \$1,950.00
7	FRONT SPONGE	1			<i>CM</i> \$450.00
8	FRONT REINFORCEMENT	1			<i>Red</i> \$3,200.00
9	FRONT GRILLE LOWER BRACKET	1			<i>Red</i> \$490.00
10	FRONT LICENSE CHROME GARNISH	1			<i>Red</i> \$2,150.00
11	SUPPORT TOP COVER	1			<i>CM</i> \$1,200.00
12	FRONT AIR GUIDE	1			<i>CM</i> \$1,750.00
13	FRONT LOWER AIR GUIDE	1			<i>CM</i> \$1,150.00
14	FRONT FENDER LH	1			<i>Red</i> \$16,000.00
15	FRONT FENDER RH	1			<i>CM</i> \$16,000.00
16	HEADLAMP LH	1			<i>my CM</i> \$12,850.00
17	HEADLAMP RH	1			<i>Red</i> \$12,850.00
18	FRONT RADIATOR GRILLE	1			<i>Red</i> \$9,100.00
19	FRONT RR EMBLEM	1			<i>Red</i> \$580.00
20	FRONT RR ORNAMENT(SPIRIT OF ECSTASY)	1			<i>Red</i> \$16,135.00
21	FRONT RADIATOR AIR DUCT LH	1			<i>Red</i> \$960.00
22	FRONT RADIATOR AIR DUCT RH	1			<i>Red</i> \$960.00
23	FRONT PARKING SENSOR	2		\$500.00	shorted \$2,000.00
24	FRONT PARKING SENSOR SEAL	2		\$100.00	nec \$400.00
25	NIGHT VISION FRONT CAMERA	1			<i>Red</i> \$6,400.00
26	CAMERA HOLDER	1			<i>Red</i> \$265.00
27	CAMERA BRACKET	1			<i>Red</i> \$100.00
28	ORNAMENT RETRACT MECHANISM	1			<i>Red</i> \$5,050.00
29	ORNAMENT COVER PANEL	1			<i>Red</i> \$1,080.00
30	BONNET	1			REPAIR
31	ORNAMENT BASE	1			<i>Red</i> \$1060.00
SUB TOTAL					\$132,240.00
COST +10%					\$13,224.00
PARTS TOTAL					\$145,464.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1218 Fax: (+65) 6472 2112

Branch

1A Serangoon North Ave 5 Singapore 554501
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Date : 03.10.2021
Vehicle No: ER5005A
Model: ROLLS ROYCE PHANTOM AUTO
Chassis: SCA687S08KU103131
Reg.Year: 2020
Policy No: SP20005397-01
Date of Accident: 28.09.2021

TO MOTOR CLAIM DEPT
Allianz Insurance
SINGAPORE PTE LTD
79 Robinson Road #09-01
SINGAPORE 068897

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	Front license plate	1		<i>me</i> \$75.00 ✓
1	FRONT FENDER CUSTOMIZED PAINT STRIPE LH	1	\$250.00	<i>me</i> \$1,500.00 ✓
1	FRONT FENDER CUSTOMIZED PAINT STRIPE RH	1	\$250.00	<i>me</i> \$1,500.00 ✓
1	COOLANT	1		<i>me</i> \$200.00 ✓
			S/N TOTAL	\$3,275.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR AT FRONT ACCIDENT AREA.

1800d
\$3,000.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ADCCIDENT AREA.

2100d
\$5,000.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

u2 \$450.00 *x*

TO CHECK WIRING & ELECTRONIC SYSTEM ETC.

\$300.00 *801*

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$300.00 *\$250/-*

TO RE-PROGRAMME FRONT SENSORS.

u2 \$350.00 *\$250/-*

TO RE-PROGRAMME HEADLAMPS.

\$1,000.00 *\$400/-*

LABOUR TOTAL \$10,400.00

TOTAL \$159,139.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

