

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SLB5499J

Model:

HONDA VEZEL

Accident Date : 12/1/2021

(13/04/16)

Location : BKE (WOODLANDS) BEFORE DAIRY FARM EXIT

3P:

SLA521R (SOMPO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear tail gate moulding <i>Carb'd</i>	356.50	✓	
2	1pc	Antenna <i>Carb'd</i>	281.30	95	
3	1pc	Tailgate handle <i>new</i>	56.40	*	
4	2pcs	Rear spare wheel board hook garnish <i>new</i>	230.40	*	
5	1pc	Front support panel centre bracket <i>Carb'd</i>	76.50	✓	
6	1pc	Front o/s head lamp bracket (Upper) <i>Carb'd</i>	43.50	✓	
7	1pc	Front o/s head lamp bracket (Lower) <i>Carb'd</i>	68.80	✓	
Sub-Total:			1,113.40	0.00	0.00
			20%	0%	0%
After Less %:			890.72	0.00	0.00
Total:			890.72		
After Less 20%:			712.58		

Chan

640.30

Admin Lg
05/10/21.

Supplementary: 512.24

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call

Mobil 1

