

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010188/RTC2**Date:** 18/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00135412101	
Claimant Vehicle No :	FBM474Z	Insured Vehicle No :	SJV3240U	
Date of Loss:	12/09/2021	Nature of Claim:	TP	Claim No: SNM21D205186/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM474Z		Engine No:	F660389
Make & Model:	TRIUMPH DAYTONA 675, 675cc		Chassis No:	SMTT12FAF658932
Reg. Date:	23/06/2017 (Man. Year: 2014)		Odometer:	49288 km
Colour:	Red			
Engine Capacity:	675 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70ZR17	Rear Tyre Size:	180/55ZR17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,618.30	5,498.90	3,119.40	36.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	510.00	390.00	120.00	23.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,128.30	5,888.90	3,239.40	35.49
+ GST 7.00/7.00% (S\$)	638.98	412.22	226.76	35.49
Nett Amount (S\$)	9,767.28	6,301.12	3,466.16	35.49

INSPECTION

Date of Assignment:	04/10/2021	
Date Inspected:	04/10/2021	Inspected At: Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Feb 2022)	
Parts:	N/A	TRIUMPH DAYTONA 675 675cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM474Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT COWLING,TOP,RED	Cracked	551.00 FL	*551.00 FL
2	1		*FRONT COWLING,BOTTOM,RED	Cracked	522.00 FL	*522.00 FL
3	1		*RH MIRROR	Scratched	155.00 FL	*155.00 FL
4	1		*DAY RUNNING LIGHT	Cracked	68.00 FL	*68.00 FL
5	1		*GARNISH,INTAKE DUCT,SILVER	Cracked	128.00 FL	*128.00 FL
6	1		*AIR INTAKE DUCT	Cracked	68.00 FL	*68.00 FL
7	1		*MAIN FRONT STAY	Cracked	290.00 FL	*290.00 FL
8	1		*HEADLAMP ASSY	Broken	698.00 FL	*698.00 FL
9	4		*GROMMETS,HEADLAMP	Necessary	24.00 FL	*24.00 FL
10	1		*RUBBER GASKET,MAIN FRONT STAY	Cracked	79.00 FL	*79.00 FL
11	1		*INTAKE FOAM PADS SET,MAIN STAY	Necessary	74.00 FL	*74.00 FL
12	1		*GROMMET,RH DASH	Necessary	7.00 FL	*7.00 FL
13	1		*RH FRONT BRAKE DISC	Scratched	487.00 FL	*487.00 FL
14	1		*RH HANDLEBAR,SILVER	Scratched	195.00 FL	*195.00 FL
15	1		*RH FRONT SIGNAL ASSY	Broken	77.00 FL	*77.00 FL
16	4		*RIVET SCREWS,FRONT LOWER SPOILER	Necessary	14.00 FL	*14.00 FL
17	1		*RH CENTRE FAIRING RED	Scratched	420.00 FL	*420.00 FL
18	1		*BRAKE PEDAL	Scratched	144.00 FL	*144.00 FL
19	1		*KNOB,UNDER RH FRONT FOOTREST	Not Necessary	16.00 FL	*- FL
20	1		*EXHAUST MUFFLER,ORIGINAL	Bent	882.00 FL	*882.00 FL
21	1		*BAR END SLIDER RH-MOTOVATION	Scratched	25.00 FS	*25.00 FS
22	1		*SET FRONT WHEEL AXLE SLIDERS KIT,MOTOVATION	Scratched	95.00 FS	*95.00 FS
23	1		*SET WINDSHIELD,AFTERMARKET,BLACK TINT	Not Necessary	285.00 FS	*- FS
24	1		*FRONT NO PLATE	Not Necessary	10.00 FS	*- FS
25	1		*SET DECALS,WINDSHIELD	Not Necessary	60.00 FS	*- FS
26	1		*LEVERS,CNC,AFTERMARKET	Scratched	225.00 FS	*225.00 FS
27	1		*BAR END KIT,AFTERMARKET	Scratched	118.00 FS	*118.00 FS
28	1		*SET FRONT MUDGUARD,CARBON FIBRE (CARBON 2 RACE)	Cracked	420.00 FS	*420.00 FS
29	1		*EXHAUST MUFFLER,ARROW	Not Necessary	2,750.00 FS	*- FS
30	1		*EXHAUST GUARD,R&G	Scratched	115.00 FS	*115.00 FS
31	1		*FRONT LOWER SPOILER,V-SHAPE	Cracked	118.00 FL	*118.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,120.00	5,999.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	501.70	500.10
Total Parts (\$\$)	8,618.30	5,498.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	60.00	40.00
2	LABOUR CHARGE	New	450.00	350.00
Gross Labour Cost (S\$)			510.00	390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >